# Other Area 3 Former UST PL-23 Interim Measures Completion Report

Boeing—Plant 2 Seattle, Washington

Submitted To:
The Boeing Company

February 1999

Plant 2 Remediation

**WF 99.1** 

Working File



# Other Area 3 Former Underground Storage Tank PL-23 Interim Measures Completion Report

Boeing—Plant 2

Submitted to

The Boeing Company Seattle, Washington

February 1999

Prepared by

Roy F. Weston, Inc. 700 Fifth Avenue Suite 5700 Seattle, WA 98104-5057

WO: 3709-034-410-0004

#### TABLE OF CONTENTS

Sect	ion Page
1.	INTRODUCTION
2.	DESCRIPTION OF WORK COMPLETED4
3.	ANALYTICAL RESULTS5
4.	DISPOSAL6
5.	QUALITY CONTROL6
6.	SUMMARY7
7.	REFERENCES7
API API	PENDIX A—OA3 IMPACTED SOIL DELINEATION REPORT PENDIX B—EXCAVATED AREA SOIL SAMPLING DATA PENDIX C—STOCKPILED SOIL SAMPLING DATA PENDIX D—QUALITY CONTROL CHECKLIST
	LIST OF TABLES
Tab	<u>Page</u>
1	OA3 Soil COC Concentrations
2	OA3 Groundwater COC Concentrations
3	Excavated Area Confirmatory Soil Sample Data

#### LIST OF FIGURES

<u>Figure</u>	<u>Title</u>
1	Site Map
2	OA 3 Soil and Groundwater Sampling Locations
3	OA 3 Excavation Plan
4	Soil Stockpile Sample Locations

## OTHER AREA 3 FORMER UNDERGROUND STORAGE TANK PL-23 INTERIM MEASURES COMPLETION REPORT

#### 1. INTRODUCTION

This Interim Measures Completion Report (IMCR) describes the results of work performed during removal of soil associated with former underground storage tank PL-23 (UST PL-23). This area is also known as Other Area 3 (OA3).

#### 1.1 Background

Located south of Building 2-80 was a former UST identified as PL-23. Figure 1 shows the approximate location of the tank. PL-23 had a capacity of 1,000 gallons and was initially installed in 1951. This tank was used to store gasoline. PL-23 was removed in 1992. A visual inspection performed at the time of removal found exterior surface corrosion over the tank's surface. The most severe corrosion was found at the discharge piping. No holes were evident in the tank (Groundwater Technology 1992). Soil immediately underneath the tank appeared to be stained and had a moderate odor. During tank removal, 5 cubic yards of impacted soil was removed. Additional soil near the tank could not be removed due to its location adjacent and under the foundation of Building 2-80. A tank removal report was prepared and submitted to the State of Washington in 1992 (Groundwater Technology 1992).

Gasoline-range hydrocarbons were detected in soil samples taken from the north and south wall of the excavation as well as from a soil boring sample collected north of the former tank. The gasoline and benzene, toluene, ethylbenzene, and xylene (BTEX) concentrations were highest in the uppermost 8 feet of the soil column. Below 8 feet, gasoline/BTEX was detected but was lower in concentration. Figure 2 shows the location of the former tank, the approximate size of the original excavation, and soil and groundwater sample locations. Tables 1 and 2 provide the concentrations of gasoline and BTEX constituents in soil and groundwater associated with each of these locations.

Based on the use of this tank, gasoline ranged hydrocarbons were determined to be the contaminants of concern (COCs). Lead, a potential constituent of gasoline, was not found in dissolved groundwater concentrations exceeding ambient water quality criteria (WESTON 1997a). Therefore, lead was not included as a COC.

To define the southern boundary of the impacted soil, three additional soil borings were completed at distances of 15, 40, and 60 feet south of the tank location. Samples were collected at depths of 3, 6, and 9 feet in each boring and analyzed for total petroleum hydrocarbonsgasoline (TPH-G) and BTEX. No detectable concentrations of BTEX or TPH-G were found in any of the samples. The two groundwater monitoring wells on each side of the former tank (MW304A and 305A) were tested for floating product. No floating product was found in the wells. A report describing the results of this delineation effort is provided in Appendix A.

The above information, along with RCRA Facility Investigation (RFI; WESTON 1997b) data, indicated the impacted soil did not extend more than a few feet from the tank excavation sidewalls. Groundwater was not appreciably impacted.

**Table 1—OA3 Soil COC Concentrations** 

Sample No.	Depth (ft)	TPH-G (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethylbenzene (mg/kg)	Xylene (mg/kg)
SB-08603	7.5	ND	NA	NA	NA NA	NA
	10	ND	NA	NA	NA	NA
	12.5	NA	NA	NA ·	NA	NA
SB-08005	2	2,100	ND	ND	ND	2
,	7	ND :	ND	ND	ND	ND
	11	ND	0.009	ND	0.001	0.005
SB-08006	5	ND	NA	NA	NA	NA
	7.5	ND	NA	NA	NA	NA
	10	ND	NA	NA	NA	NA
SB-08007	5	ND	NA	NA	NA	NA
	7.5	ND	NA	NA	, NA	NA
	10	ND	NA	NA	NA	NA
SB-08009	0.6	ND	ND	ND	ND	NA
	6	ND	ND	ND	ND	NA
SB-08013	5	ND	NA	NA	NA	NA
	9	ND	NA	NA	NA	NA
	12	ND	NA	NA	NA	NA
SB-08015	4	ND	ND	ND	ND:	ND
	7	ND	ND	ND	ND	ND
	9	ND	ND	ND	ND	ND
EX-1	8	1,200	49	650	260	1,400
EX-3	8	14,000	1.9	9.9	11	76
EX-5	10.5	19	0.28	ND	0.28	0.86

NA: Not Analyzed ND: Not Detected

Table 2—OA3 Groundwater COC Concentrations

Sample No.	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Xylene (μg/L)	TPH-gasoline (mg/L)
GP-08001	ND	1.6	ND	ND	ND
GP-08002	ND	ND	ND	ND	ND
GP-08003	ND	ND	ND	ND	ND
GP-08007	ND	ND	ND	ND	ND
PL2-304A	48	ND	45	ND	NA
PL2-305A	ND	ND	ND	, ND	NA

NA: Not Analyzed ND: Not Detected

The portion of Building 2-80 near OA3 was demolished and a new building is being constructed over this site. As a result, access to the impacted soil was now possible. It was decided to remediate OA3 by removing soil containing TPH-G and BTEX to allow unimpeded construction of the new facility.

#### 1.2 Interim Measures Objectives

The Interim Measures Objectives for this project were:

- Remove impacted soil to allow renovation of Building 2-80. Remove soil to the extent that no potential future risks to human health or the environment above accepted guidelines are likely given the proposed use of the facility.
- Remove soil to the extent that it will be at least as protective as final remedies selected for similar sites in the corrective measures study (CMS).
- Provide a timely response to mitigate "short-term" construction risks associated with exposure of contaminants.

The soil cleanup levels for Plant 2 have not yet been established by the U.S. Environmental Protection Agency (EPA). Washington State Department of Ecology Model Toxics Control Act (MTCA) Method A as specified in WAC 173-340-745 was used as numerical targets in lieu of EPA-approved cleanup levels. The criteria specified therein for BTEX are 0.5, 40.0, 20.0, and 20.0 mg/kg, respectively. The cleanup level for gasoline is specified as 100 mg/kg.

The excavation goal in the work plan (WESTON 1997c) was to remove soil to a depth of 10 feet (anticipated groundwater depth) or until groundwater was encountered. Any contaminated soil remaining below the groundwater table would be addressed as a groundwater issue if necessary. Because of the small size of the impacted soil area, the sandy nature of the soil and the presence of a storm drain running through the site, removal below the groundwater table was not practical.

#### 2. DESCRIPTION OF WORK COMPLETED

Foss Environmental was contracted by WESTON to perform the construction work. Foss Environmental reported to WESTON. WESTON, in turn, reported to Boeing's onsite engineer. The IM scope of work was prepared by WESTON.

A utility survey of the site was completed. A storm drain, electrical duct bank, and fire main ran through the site. A roof drain was also present. The electrical duct bank was confirmed to be deenergized and the fire main had been shut off prior to building demolition.

The area to be excavated was measured and marked with yellow spray paint. The asphalt was peeled back on Wednesday, 25 March 1998. A stockpile area was set up using jersey barriers and plastic.

Excavation of the soil began on Thursday, 26 March 1998. Prior to excavation, straw bales were placed around a catch basin located southeast of the area to be excavated. Foss Environmental was the contractor responsible for soil removal. WESTON personnel on-site included a field sampler and a construction manager. The field sampler was equipped with an organic vapor monitor (OVM). The OVM was used to sniff the soil to determine which soil was contaminated and needed to be stockpiled separately from clean soil (i.e., no vapors detectable). The intent was to keep the contaminated soil separate from the clean soil. Upon stockpile confirmatory sampling, the clean stockpiled soil would be reused and the contaminated soil would be sent to an off-site disposal facility.

Soil excavation began on the north side of the area marked for removal. The first few backhoe buckets of soil had very low OVM vapor readings (1 to 2 units). These readings were similar to background readings indicating the soil was potentially noncontaminated. After 1 cubic yard of soil had been excavated, the OVM readings started to increase. Upon reaching the elevated OVM readings so quickly, it was decided to place the impacted soil in the same location as the initially excavated clean soil since the quantity of clean soil was small.

The OVM readings from the stockpiled soil kept increasing. When the excavation reached a depth of approximately 4 feet on the north side, a light-gray fine soil lens was encountered that had a strong odor of weathered gasoline. The lense was approximately 1 to 2 feet thick. OVM reading of this soil hit a maximum of 75 units. The stained soil lense was excavated northward until visibly removed. Sidewall soil was sniffed and found to have background OVM readings.

Excavation continued downward to a depth of 8 feet where pooling water began to occur. Soil collected from beneath the impacted lense was sniffed and found to have low to no OVM readings. Soil collected from the bottom of the excavation also had low background OVM readings. Soil excavation then began in a southward direction after attaining a depth of 8 feet. The impacted soil lense did not extend far to the south. Overall, the lense was approximately 15 feet (east-west direction) by 5 feet (north-south) by 1 to 2 feet thick.

Low OVM readings (5 units) were observed in soil excavated to the south of the lense. This soil was placed on the impacted stockpile. Excavation continued southward at a depth of 8 feet until

it reached 4 feet from the location of the storm drain. Inspection of the storm drain manhole indicated the top of the drain was located approximately 7 feet below ground surface.

The depth of the excavation was decreased to approximately 5 feet to allow 2 feet of clearance over the drain. Excavation continued south at a depth of 5 feet until it was 4 feet past the southern edge of the drain. The depth of excavation at that point was increased to 7 feet to allow support for the drain. Soil over the drain continued to have low to no OVM readings. This soil was placed in the non-contaminated soil stockpile.

The excavation continued southward. Soil from the bottom and sidewall area south of the storm drain had no OVM readings and was also segregated from the impacted soil. Soil was excavated until it was approximately 3 feet north of soil boring SB-08015, which had been used to define the southern extent of the impacted area as discussed previously.

At key points during excavation, discrete soil samples were taken from within the excavation for laboratory analysis. One sample was collected from the north sidewall at an elevation of 6 feet from the top. Another sample from the excavation bottom was collected. A third sample was collected from the south sidewall at an elevation of 5.5 feet below the top. All samples were taken by removing outer material and exposing inner soil for sampling. Because of the excavation depth, soil samples were collected with the backhoe bucket.

Figure 3 shows the final excavation configuration and confirmatory soil sample locations.

When the former tank excavation was completed, soil stockpiles were covered with plastic and weighted down.

On Tuesday, 31 March 1998, the two soil stockpiles were sampled for disposition. Three grab samples were collected from each stockpile where the field OVM indicated the highest readings. The samples were placed directly into sample jars. Soil samples were collected by removing the outer 1 foot of material and collecting a soil sample from the interior of the stockpile. The impacted soil stockpile was estimated to contain 40 cubic yards and the potentially nonimpacted stockpile was estimated to contain 40 cubic yards.

Confirmatory and stockpile soil sampling was performed in accordance with Washington State Department of Ecology guidance (Ecology 1992).

The final soil conditions at OA 3 have no potential to further impact groundwater. The wells were removed, the soil where the monitoring wells were located was removed and the soil with elevated concentrations of gasoline/BTEX was removed.

#### 3. ANALYTICAL RESULTS

The results of confirmatory excavation sampling is shown in Table 3 below. Sample data are provided in Appendix B.

**Table 3—Excavated Area Confirmatory Soil Sample Data** 

Sample No.	Benzene (µg/kg)	Toluene (µg/kg)	Ethylbenzene (µg/kg)	Xylene (µg/kg)	TPH-gasoline (mg/kg)
SB08032-0060	62U	62U	62U	100	6.2U
SB08033-0055	56U	56U	56U	56U	5.6U
SB08034-0080	58U	58U	58U	58U	5.8U

Note: U indicates the constituent was not detected at the listed detection limit.

The analytical data reflects mostly nondetectable concentrations of confirmatory constituents. Detected constituents are below their respective MTCA cleanup concentrations.

#### 4. DISPOSAL

Three discrete soil samples were taken from each stockpile. The stockpile sample locations are shown in Figure 4. Complete soil stockpile data used for disposal characterization are provided in Appendix C.

Decontamination of personnel, sampling equipment and excavation machinery generated approximately 3 gallons of decontamination solutions. These decontamination solutions were distributed over the designated "impacted" soil stockpile for disposal.

The impacted soil was taken to Columbia Ridge Landfill, Arlington, Oregon. The nonimpacted soil was reused as fill on-site.

#### 5. QUALITY CONTROL

Sampling procedures followed Washington state guidance for Site Checks and Site Assessments for Underground Storage Tanks. Sampling equipment was decontaminated after each sampling episode using alconox and a deionized water rinse. Samples were placed into clean jars and chain-of-custody forms completed.

Upon completion of sampling, the confirmatory samples were taken directly to Analytical Resources, Inc., for analysis.

BTEX was measured using EPA Method 8020. Laboratory spikes and blanks were run to confirm the validity of the analytical results. Gasoline was determined using gas chromatography/flame ionization detection (GC/FID) methods.

A Quality Control checklist was used to ensure quality of the work and that the removal requirements were met. This checklist provided inspection points within the work. The completed checklist is provided in Appendix D.

#### 6. SUMMARY

The objectives of the interim measure were achieved. Soil remaining at OA3 has essentially nondetectable concentrations and is well below the MTCA Method A cleanup goals for BTEX and gasoline. Stockpiled soil was characterized and properly disposed.

#### 7. REFERENCES

Groundwater Technology. 1992. Tank Removal Report- UST PL-23, Prepared by Groundwater Technology, Inc., December 1992.


Ecology (Washington State Department of Ecology). 1992. Guidance for Site Checks and Site Assessments for Underground Storage Tanks. Publication No. 90-52.

WESTON (Roy F. Weston, Inc.). 1997a. RCRA Facility Investigation, Groundwater Investigation Interim Report. Prepared for The Boeing Company. Roy F. Weston, Inc. August.

WESTON. 1997b. RCRA Facility Investigation, Soil Investigation Interim Report. Prepared for The Boeing Company. Roy F. Weston, Inc. August.

WESTON. 1997c. OA3 Former UST PL-23 Interim Measures Work Plan. Prepared for The Boeing Company. Roy F. Weston, Inc. March.


#### **FIGURES**



Site Map

FIGURE

1



#### **EXPLANATION**


- ⊗ Soil Boring
- Monitoring Well
- O Geo-Probe






Boeing – Plant 2 OA 3 Soil and Groundwater Sampling Locations








#### **EXPLANATION**

Soil Sample Locations



Boeing – Plant 2 Soil Stockpile Sample Locations



Figure 4

#### APPENDIX A

#### OA3 IMPACTED SOIL DELINEATION REPORT



Roy F. Weston, Inc. Suite 5700 700 5th Avenue Seattle, Washington 98104-5057 206-521-7600 • Fax 206-521-7601

31 October 1997

Mr. Skip Fox Project Geologist Information Support Services Energy and Environmental Affairs PO Box 3707, MS 7A-XA Seattle, WA 98124-2207

WO 3709-34-403-0001

Subject: OA3 Former Underground Storage Tank

Dear Skip:

Attached is a brief report documenting the results of the investigation to define the extent of gasoline impacted soil at Other Area 3 "Former UST PL-23." The most recent data (in addition to the RFI data) indicate that the gasoline in soil is confined to a relatively small localized area around the former tank.

Because the estimated quantity of soil is small, it may be most efficient to address this soil during Building 2-81 construction rather than remove it under its own Interim Measure.

If you have questions, please call me at 521-7692

Sincerely,

ROY F. WESTON, INC.

Larry Vanselow Project Manager

Attachment

cc:

R. Rogers Project file

#### **OA3 SOIL**

#### **INVESTIGATION RESULTS**

#### INTRODUCTION

Other Area (OA) 3 was the site of former underground storage tanks. Based on data collected during tank removal and from the RCRA Facilities Investigation (RFI), soil in OA 3 was found to contain gasoline and components of gasoline. Gasoline concentrations as high as 14,000 mg/kg have been noted.

During the RFI, the extent of gasoline-impacted soil was relatively well bounded on the north, west, and east sides. However, to support renovation of Building 2-80, the extent of gasoline-impacted soil on the south side of OA3 was required.

This document provides a summary of work performed and the results of soil sampling to define the southern extent of the OA 3 gasoline-impacted soil.

#### **WORK PERFORMED**

Three borings (SB-08015, SB-08016 and SB-08017) were completed in the southward direction of OA 3. The borings were located at distances of 15, 40, and 60 feet from the former underground storage tank.

Samples were collected at depth of 3 feet, 6 feet and 9 feet in each of the three borings. The samples were sent to ARI for TPH-g and VOC analysis. In addition, during sample collection, an Hnu was used to "sniff" the soil for volatiles.

Upon completion of the borings, the holes were filled with bentonite chips.

Groundwater monitoring wells 304A and 305A were checked for floating product.

#### **RESULTS**

The Hnu detected no vapors in any of the soil samples collected. Analytical results were also non-detect, indicating no gasoline is present in the most recent samples outbound of the former tank location. The analytical results are attached.

No floating product was found in monitoring wells 304A and 305A.

Based on new and existing information, the maximum quantity of impacted soil is estimated at 200 cubic yards. It is likely that the actual quantity of impacted soil is much smaller—on the order of 50 cubic yards.

0 A3

9 September 1997

Skip Fox
The Boeing Company
Information and Support Services
P.O. Box 3707, M/S 7A-XA
Seattle, WA 98124-2207

RE: Plant 2 Soil Analysis ARI Job T588 RECEIVED

SEP 1 1 1997

ROY & WESTON, INC. SEATTLE OPERATIONS

Dear Skip:

Please find enclosed a sample custody record and a final analytical data set for the above referenced project. Nine solid samples were received in good condition from Roy F. Weston, Inc. on August 27, 1997.

As requested, samples were analyzed for gasoline range hydrocarbons referencing WDOE method WTPH-g and for volatile aromatics referencing EPA method 8020. The sample reports show raised detection limits for toluene due to background interference (see "Y" flag).

No other analytical complications were noted for this delivery group. Quality control analysis results are included for your review. Copies of the reports and all associated raw data will be kept on file. If you have any questions or require additional information, please contact me at your convenience.

Sincerely,

ANALYTICAL RESOURCES, INC.

Jeff J. Reitan

Project Management

jeffr@cnw.com

JJR/jr Enclosure

Lifetosure


cc: Rudy Rogers, The Boeing Company (M/S 19-16)

Roger McGinnis, Roy F. Weston, Inc.

## **Chain of Custody Record & Laboratory Analysis Request**

Date: 8/27/97

Page / of 2



nt: BOEING.		· · · · · · · · · · · · · · · · · · ·	e#: 5	21-1	668	Coole	r Temp	: <u>N</u>	H				621-7523 (Fax)
ontact: Rozer Mc	Gin	という	***************************************	~		Analysis Required							Notes/Comments
<del></del>			001-	00		13	. 7						97-15041
s: SINLIMITH	ask	UR.	<b>,</b>			15	7						40 97-15049
Sample ID	Date	Time	Matx	No Cont	Lab ID	1	B						-17-1209-1
3-08045-0040	8/21	2 0955	Soil	1		<b>V</b>	V						
3-080015-0070		1015		1		V	V						
3-080015-0090		1030		/		V	V						
3-080016-0030	_	1105		/_		V	/					· .	
-080016-0060		1115	1	1		1	V						
3-080016-0090		1/25		1		V	V					-	
-080017-0030	•	1210		1	1								
ect No: 1588	Relina (Signa	quished by ature)	has	A		Relinquished by: (Signature)			Relir (Sigr	Relinquished by: (Signature)			
quested:	Printe	ed Name:	i CHA.	RD 5	TURI	Prir	nted Na	me:			Print	ted Nai	me:
its/Special Instructions:	Comp	pany: W	esto	$ \sqrt{} $		Cor	npany:			-	Com	pany:	
	Date:	8/27/0	77 Tin	ne:/5	55	Dat	e:		Time:		Date	<b>:</b>	Time:
•	Recei (Signa	ived by:	oru Z	0 - nu t	OX	Rec (Sig	cived k nature)	oy:					y:
	Printe		70			Prir	nted Na	me:			Print	ed Nai	ne:
			I			Cor	Company:			Com	Company:		
	Date:	8/27/9	7 Tin	ne: /5	55	Dat	e:		Time:		Date	):	Time:
	Sample ID S-080015-0090 S-080016-0030	ontact: Rozer McGins roject ID: 03709-034-9 s: STULIM/THEASI Sample ID Date 3-080015-0070 3-080015-0090 3-080016-0030 3-080016-0060 3-080016-0090 3-080017-0030 act No: 1588 Relin (Sign: Quested: Printe ats/Special Instructions: Compared: Received (Sign: Compared)	ontact: Rozer McGinsuis  roject ID: 03709-034-403-00  s: STULIM/Thrashor  Sample ID Date Time  3-080015-0070 1015  3-080015-0070 1030  3-080016-0030 1/05  3-080016-0090 1/15  3-080016-0090 1/15  3-080017-0030 1/15  Get No: 1588 Relinquished by (Signature) 1015  ats/Special Instructions: Company: Water Printed Name: Received by: ats/Special Date: 8/27/2018	Sample ID Date Time Matx  Sample ID Date Time Matx  Sample ID Date Time Matx  S-080015-0070 1015 1  S-080015-0090 1030 105  S-080016-0030 115  S-080016-0060 1115  S-080017-0030 125  S-080017-0030 1210 125  S-080017-0030 125	ontact: Rozer McGinis  roject ID: 03709-034-403-0001-00  s: STURIM/Thrasher  Sample ID  Date Time Matx Cont  3-080015-0070 1015 1  3-080015-0090 1030 1  3-080016-0030 1105 1  3-080016-0030 1115 1  3-080016-0060 1115 1  3-080016-0060 1115 1  3-080016-0090 125 1  3-080016-0090 1  3-0	Sample ID Date Time Matx No Lab Sample ID Date Time Matx No Lab Sample ID Date Time Matx No Lab B-080015-0070 1015 1 B-080015-0070 1030 1 B-080016-0030 1105 1 B-080016-0060 1115 1 B-080016-0060 1115 1 B-080017-0030 125 1 B-080017-0030 1 B-080	ontact: Rozer McGinsuis  roject ID: 03709-034-403-0001-00  s: 57 W. M. / The asker  Sample ID Date Time Matx Cont ID  3-08045-0040 827 0955 501/ 1  3-080015-0070 1015 1  3-080015-0090 1030 1  3-080016-0030 105 1  3-080016-0030 115 1  3-080016-0090 115 1  3-080016-0090 115 1  4-080016-0090 1  4-080016-0090 1  4-080016-0090	Sample ID   Date   Time   Matx   No   Lab   Lab   No   Lab   No   Lab   No   No   No   No   No   No   No   N	Ana Project ID: 03709-034-403-0001-00  Sample ID  Date  Time  Matx  No ID  No	Analysis Required Formulation Structure of the Content of the Cont	Analysis Required  Toject ID: 03709-034-403-0001-00  Signature)  Time Matx No Lab  B-080015-0090 1015 1 VV  B-080015-0090 1030 1 VV  B-080016-0060 1115 1 VV  B-080016-0060 1115 1 VV  B-080016-0060 1115 1 VV  B-080016-0070 1015 1 VV  B-080016-0070	Analysis Required  Toject ID: 03709-034-403-0001-00  Signature)  Received by: (Signature)  Received by: (Signature)	Analysis Required  Analysis Anal

Limits of Liability: ARI will perform all requested services in accordance with appropriate methodology following Standard Operating Procedures and our Quality Assurance Program. This program meets standards for the industry. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed the invoiced amount for said services. The acceptance by the client of a proposal for services by ARI releases ARI from any liability in excess thereof, not withstanding any provision to the contrary in any contract, purchase order or co-signed agreement between ARI and the client.

# **Chain of Custody Record & Laboratory Analysis Request**

Date: 8/27/97Page 2 of 2Number of coolers:



Analytical Resources, Incorporated Analytical Chemist and Consultants 400 Ninth Avenue North Seattle, WA 98109-4708 (206) 621-6490

ARI C	Client:	BOEINS		Phon	e#: 54	21-76	68	· ·						(206) 621-7523 (Fax)				
Clien	t Conta	ct: Rosen O	1cg.x	2115				Analysis Required					1	Notes/Comm	ents			
		ct ID: 03709-0			<b>2</b> 0		,	٦	ar									
Samp		STURIM						W	7	2								
		Sample ID	Date	Time	Matx	No Cont	Lab ID	10	2									*
1 4	5B-0		8/27	1215	Soil	1		V	/									
2 2	SR-C	80017-0065 080017-0090	8/27	1225	Soll	1		V	V									
3							·										Manager (1)	
4										=1								
5								-										
6										-	-							
7							4											
ARI P	roject N	No:	Relinqi (Signat	uished by	Kil	1/1		Rel (Sig	inquish gnature	ed by	′ <b>:</b>	<u> </u>		Rel (Sig	inquish nature	ned by:		
T.A.T.	Reque	sted:	Printed	Name:	D 570	LR.F	) 1		Printed Name: Printed					<del></del>				
Comr	nents/S	pecial Instructions:		iny:we			(No	) Cor	mpany:		********************************			Cor	npany	:		
			Date:			ne:/S	35	Dat	te:		Tin	ne:		Dat	e:		Time:	,
	:		Receiv (Signat	ed by:	· · · ·	Lou.	Zux	Red (Sig	ceived   gnature	oy:				Rec (Sig	eived nature	by: )		
				Name	74/	بر برد - آگر س دیم	改		nted Na						nted Na			
			Compa	any: An	7			Col	Company: Com					npany:				
			Date:	8/77/0	ァ タフ <sup>Tir</sup>	ne: /5	56	Da	te:		Tin	ne:		Dat	e:		Time:	
				0121	<u> </u>	17						·	27 17 2190			<del></del>		

Limits of Liability: ARI will perform all requested services in accordance with appropriate methodology following Standard Operating Procedures and our Quality Assurance Program. This program meets standards for the industry. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed the invoiced amount for said services. The acceptance by the client of a proposal for services by ARI releases ARI from any liability in excess thereof, not withstanding any provision to the contrary in any contract, purchase



### TOTAL GASOLINE RANGE HYDROCARBONS WTPHG Range Toluene to C12 by GC/FID

QC Report No:

T588-Boeing Corporate SHEA

Matrix: Soil

Project: 03709-034-403-0001-00

Data Release Authorized MB Date Received: 08/27/97

Reported: 09/09/97

Lab ID	Client Sample ID	Date Analyzed	Dilution Factor	Gas Ra Hydrocar	_	Gasoline ID	Surr A Rec	Surr B Rec
T588-0904MB	Method Blank	09/04/97	1:1	5.0	U	NO	91.0%	75.4%
97-15041-T588A	SB-080015-0040	09/04/97	1:1	5.0	U	NO	93.4%	80.3%
97-15042-T588B	SB-080015-0070	09/04/97	1:1	5.0	U	NO	86.4%	70.4%
97-15043-T588C	SB-080015-0090	09/04/97	1:1	6.1	U	NO	80.6%	70.2%
97-15044-T588D	SB-080016-0030	09/04/97	1:1	5.0	U	NO	98.7%	81.8%
97-15045-T588E	SB-080016-0060	09/04/97	1:1	6.3	υ.	NO	85.1%	72.4%
97-15046-T588F	SB-080016-0090	09/04/97	1:1	7.6	U	NO	83.3%	72.3%
97-15047-T588G	SB-080017-0030	09/04/97	1:1	5.0	U	NO	96.6%	83.9%
97-15048-T588H	SB-080017-0065	09/04/97	1:1	5.3	U	NO	95.6%	85.9%
97-15049-T588I	SB-080017-0090	09/05/97	1:1	5.0	U	NO	86.5%	76.0%

Surrogate A is Trifluorotoluene. Surrogate B is Bromobenzene.

Values reported in ppm (mg/kg) on a dry weight basis.

Quantitation on total peaks in the gasoline range from Toluene to C12.

- U Compound not detected at the given detection limit.
- X Value detected above linear range of instrument. Dilution required.
- J Indicates an estimated value below the calculated detection limit.
- S No value reported due to saturation of the detector. Pilution required.
- D Indicates the surrogate was not detected because of dilution of the extract.
- NR Indicates no recovery due to matrix interference.



#### TOTAL GASOLINE RANGE HYDROCARBONS WTPHg Range Toluene to C12 by GC/FID

Lab Sample ID: T588SB QC Report No: T588-Boeing Corporate SHEA

LIMS ID: 97-15041

Project: 03709-034-403-0001-00

Matrix: Soil

Data Release Authorized: ONB

Reported: 09/09/97

LABORATORY CONTROL SAMPLE RECOVERY REPORT Analyzed 09/04/97

CONSTITUENT		SPIKE FOUND	SPIKE ADDED	% RECOVERY
LABORATORY CONTROL SAMPLE				
Gasoline Range Hydrocarbon	s	2.23	2.5	89.2%

#### TPHg Surrogate Recovery

Trifluorotoluene Bromobenzene

98.7%

Values reported in parts per million (mg/kg)

TPHg SPIKE CONTROL LIMITS

Percent Recovery

80.0-120%

Advisory QA Limits



ANALYTICAL RESOURCES **INCORPORATED** 

SB-080015-0040 Sample No:

Lab Sample ID: T588A

LIMS ID: 97-15041

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: 8.4%

Sample Amount: 0.053 g

Dilution Factor:

#### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	47	υ
108-88-3	Toluene	190	Y
100-41-4	Ethylbenzene	47	U
	m,p-Xylene	47	U
95-47-6	o-Xylene	47	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 99.1% Bromobenzene 84.1%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Indicates a value above the linear range of the detector. Dilution Required
- s Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



ANALYTICAL RESOURCES INCORPORATED

Sample No: SB-080015-0070

Lab Sample ID: T588B

LIMS ID: 97-15042 Matrix: Soil QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97 Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97 Percent Moisture: 20.5%

Sample Amount: 0.052 g

Dilution Factor: 1

#### Reported in Total ug/kg Dry Weight

CAS Number	Analyte		Value	A.
Service Control				
71-43-2	Benzene	5 %	48	U
108-88-3	Toluene		190	Y
100-41-4	Ethylbenzene		48	U
	m,p-Xylene		48	U
95-47-6	o-Xylene		48	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 91.7% Bromobenzene 75.3%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- E Indicates a value above the linear range of the detector.
  Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- B Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences.

  The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



ANALYTICAL **RESOURCES INCORPORATED** 

Sample No: SB-080015-0090

Lab Sample ID: T588C

LIMS ID: 97-15043

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: 28.7%

Sample Amount: 0.041 g

Dilution Factor: 1

Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	61	U
108-88-3	Toluene	240	Y
100-41-4	Ethylbenzene	61	U
	m,p-Xylene	61	U
95-47-6	o-Xylene	61	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 85.1% Bromobenzene 74.1%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- Indicates the surrogate was diluted out. D
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



ANALYTICAL RESOURCES INCORPORATED

Sample No: SB-080016-0030

Lab Sample ID: T588D

LIMS ID: 97-15044

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: 5.7%

Sample Amount: 0.053 g

Dilution Factor: 1

Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value		
71-43-2	Benzene	47 U		
108-88-3	Toluene	190 Y		
100-41-4	Ethylbenzene	47 U		
	m,p-Xylene	47 U		
95-47-6	o-Xylene	47 U		

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 103% Bromobenzene 85.2%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- s Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. Y The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



**ANALYTICAL** RESOURCES **INCORPORATED** 

Sample No: SB-080016-0060

Lab Sample ID: T588E

LIMS ID: 97-15045

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: 22.5%

Sample Amount: 0.040 g

Dilution Factor: 1

#### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	63	U
108-88-3	Toluene	250	Y
100-41-4	Ethylbenzene	63	U
	m,p-Xylene	63	U
95-47-6	o-Xylene	63	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 90.4% Bromobenzene 76.5%

- Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Indicates a value above the linear range of the detector. Dilution Required
- s Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



ANALYTICAL RESOURCES **INCORPORATED** 

SB-080016-0090 Sample No:

Lab Sample ID: T588F

LIMS ID: 97-15046

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97 Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: 37.4%

Sample Amount: 0.033 g

Dilution Factor: 1

Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	!
71-43-2	Benzene	76	υ
108-88-3	Toluene	300	Ÿ
100-41-4	Ethylbenzene	76	U
	m,p-Xylene	76	U
95-47-6	o-Xylene	76	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 88.0% Bromobenzene 76.6%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. Y The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- Indicates no recovery due to interferences. NR



**ANALYTICAL RESOURCES INCORPORATED** 

SB-080017-0030 Sample No:

Lab Sample ID: T588G

LIMS ID: 97-15047 Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project:

03709-034-403-0001-00

Date Sampled:

08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Sample Amount: 0.050 g

Date analyzed: 09/04/97 Percent Moisture: 7.8%

Dilution Factor:

1

#### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value		
71-43-2	Benzene	50 U		
108-88-3	Toluene	200 Y		
100-41-4	Ethylbenzene	50 U		
	m,p-Xylene	50 U		
95-47-6	o-Xylene	50 U		

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 103% Bromobenzene 88.3%

#### Data Qualifiers

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.

#### FORM-1 BETX



ANALYTICAL **INCORPORATED** 

Sample No: SB-080017-0065

Lab Sample ID: T588H

LIMS ID: 97-15048

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/04/97 Percent Moisture: 10.9%

Sample Amount: 0.047 g

Dilution Factor: 1

#### Reported in Total ug/kg Dry Weight

CAS Number		Analyte	Value			
	71-43-2	Benzene		53	U	
	108-88-3	Toluene	1,130,000	210	Y	
	100-41-4	Ethylbenzene		53	U	
		m,p-Xylene		53	U	
	95-47-6	o-Xylene		53	U	

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 100% Bromobenzene 91.2%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- Indicates no value reported due to saturation of the detector. s
- Indicates the surrogate was diluted out. D
- В Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- Indicates compound was not analyzed. NA
- NR Indicates no recovery due to interferences.



**ANALYTICAL** RESOURCES **INCORPORATED** 

Sample No: SB-080017-0090

Lab Sample ID: T588I

LIMS ID: 97-15049

Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled: 08/27/97

Date Received: 08/27/97

Data Release Authorized:

Reported: 09/09/97

Date analyzed: 09/05/97

Percent Moisture: 19.1%

Sample Amount: 0.052 g

Dilution Factor: 1


#### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	48	U
108-88-3	Toluene	190	Y
100-41-4	Ethylbenzene	48	U
	m,p-Xylene	48	U
95-47-6	o-Xylene	48	U

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 91.3% Bromobenzene 79.6%

- Indicates compound was analyzed for, but not detected at the U given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- s Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- Indicates no recovery due to interferences. NR





#### Sample No: Method Blank

Lab Sample ID: T588MB

LIMS ID: 97-15041 Matrix: Soil

QC Report No: T588-Boeing Corporate SHEA

Project: 03709-034-403-0001-00

Date Sampled:

NA Date Received: NA

Data Release Authorized: My

Reported: 09/09/97

Date analyzed: 09/04/97

Percent Moisture: NA

Sample Amount: 0.050 g Equiv

Dilution Factor: 1

Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value		
71-43-2	Benzene	50	ΤŢ	
108-88-3	Toluene	200	-	
100-41-4	Ethylbenzene	50	U	
	m,p-Xylene	50	U	
95-47-6	o-Xylene	50	U	

#### BETX 8020 Surrogate Recovery

Trifluorotoluene 96.6% Bromobenzene 79.8%

- Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the cpinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- Indicates no recovery due to interferences. NR



Lab Sample ID: T588E

Sample No: SB-080016-0060

QC Report No: T588-Boeing Corporate SHEA
Project: 03709-034-403-0001-00

LIMS ID: 97-15045

88.1%

Matrix: Soil

Date Received: 08/27/97

Reported: 09/09/97

Data Release Authorized: BNB

MATRIX SPIKE/SPIKE DUPLICATE RECOVERY Date Analyzed: 09/04/97

CONSTITUENT	SAMP VAL			% RECOVERY	RPD		
MATRIX SPIKE							
Benzene Toluene Ethylbenzene	< 63	253 279 3.3 278	0 2960 0 2960	92.6% 94.3% 93.9%	•		
m,p-Xylene o-Xylene	< 63 < 63			92.6% 94.6%			
MATRIX SPIKE DUPLICATE	MATRIX SPIKE DUPLICATE						
Benzene Toluene Ethylbenzene m,p-Xylene o-Xylene	< 2 < 6 < 6	33.3     283       53     290       33.3     286       33.3     565       33.3     286	2990 2990 2990 5980	94.6% 97.0% 95.7% 94.5% 95.7%	2.2% 2.8% 1.9% 2.1% 1.2%		
BETX SURROGATE RECOVERI	es i	MATRIX SPIKE	MATRIX SPIKE	DUPLICATE			
Trifluorotoluene		87.8%	94.7	<b>*</b>			

Reported in Total ug/kg Dry Weight (ppb)

83.5%

BETX SPIKE CONTROL LIMITS

Bromobenzene

Percent Recovery 75-130% Duplicate RPD <30%

#### APPENDIX B

## EXCAVATED AREA SOIL SAMPLING DATA

La	boratory Analy	sis Re	gires	f <sub>A</sub> ~		€pi~	Pag	re:	of	)		U	)		Seattle, (206) 62	<b>ORATED</b> h Ave. Nor WA 98109-	5187	
Clie	ent Contact: Larry Vans	selow/k	PHCH	INN	15				Α	nalysis	Require	ed'	i Albania	**	N	otes/Com	ments	3
5	ent Project ID: 03709-	• • • • • • • • • • • • • • • • • • • •	4.5			00		10										
Sar	nplers: Sturin			1984 (A)			N	1										
	Sample ID	Date	Time	Matx	No Cont	Lab ID	8									1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		siriid se viini Tas
1	5B0B032-0060	3/24/98	1255	Soil	1		V	/								4		X 1
	5B08033-0055	3/26/98	1.1	Soil	1		V	V										
	SB08034-0080	3/24/98	<u> </u>	Soil	/		1	4						7. 7.		-		
4																		
5																		749
6	:												,		i.	- " Ville		· . :
7	·		,		1													
Co	mments/Special Instructions:	Relinquis (Signatu		21	10	1		quished nature)	d by:					quished ature)	d by:	-		
	Duick Turn-	Printed N		7/10/	1 <del>()()</del>			ed Nam	ne:		i to			ed Nan	ne:	•		
	round time.	Compar				INC.	Con	npany:				W.,.	Com	pany:				
	nesults bu		26/98		161		Date	<del></del>		Time		19	Date	<b>)</b>		Time:		
00	nesults by	Receive (Signatu	d by:	$\Omega_{I}$	161	10		elved by	y:					eived b ature)	y:			
		Printed N		Len	od i			ed Nam	ne:	- ,:	24.			ed Nan	ne:			
	•	Compar	<del></del>	七	<u></u>		Con	npany:					Com	pany:			Ž. 11. s	o Agr
1.2		Date:7	17619	18 <sup>Time</sup>	: [[0	20	Date	<b>):</b>		Time			Date			Time:		

ANALYTICAL

Limits of Liability: ARI will perform all requested services in accordance with appropriate methodology following Standard Operating Procedures and our Quality Assurance Program. This program meets standards for the industry. The total liability of ARI, it's officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed the involced amount for said services. The acceptance by the client of a proposal for services by ARI releases ARI from any liability in excess thereof, not withstanding any provision to the contrary in any contract, purchase order or co-signed agreement between ARI and the client.



2 April 1998

Rudy Rogers
The Boeing Company
P.O. Box 3707, M/S 19-16
Seattle, WA 98124-2207

RE: Project: 03709-034-410-0002-00 ARI Job V838

Dear Rudy,

Please find enclosed original chain of custody records and analytical results for the above referenced project. Analytical Resources, Inc. accepted three soil samples in good condition on March 17, 1998.

The samples were analyzed for BTEX and TPH-gasoline referencing US EPA SW-846 method 8020 and 8015-gasoline, respectively. Quality control analysis results are included for your review.

No analytical complications were noted. Copies of the reports and all associated raw data will be kept on file at ARI. If you have any questions or require additional information, please contact me at your convenience.

Sincerely,

ANALYTICAL RESOURCES, INC.

Jeff J. Reitan Project Manager

jeff@arilabs.com

JJR/jmb Enclosure

Cc: Joe Johnson, The Boeing Company, M/S 7A-XA Roger N. McGinnis, Roy F. Weston (Seattle, WA)

M. Bri for Jeff Reitan

PECEIVED

APR - 3 1998

ROY P. WESTON, INC. SEATTLE OPERATIONS

		BOEI	Na	· .			Al	NALYTICAL	U
Chain of Custody	Record 8	& BOE!	sou .	Date: $\frac{3/2}{2}$	6/98		RE	SOURCES CORPORATED	
Laboratory Analys	SIS REQUE		1	Pagec	of		S€	33 Ninth Ave. North eattle, WA 98109-5187	
ARI Client: Wester	Phone #	206-521-7	668	Number of coo	lers: _ /	(5.0		06) 621-6490 06) 621-7523 (FAX)	
Client Contact: Largy Vaus	2/0W/K.170	GINNIS			Arialysis Req	uired		Notes/Comment	ts ,
Client Project ID: 03709-	034-410	-0002-	00	10	1			18-5771	6 +
Samplers: Sture M		No	Lab	14				98-57	18
Sample ID	Date Tim		1 1	10 K				V838	
1 5B0B032-0060	3/24/98 1253	5 Soil 1		VV					
25B08033-0055	3/26/98 152	D Soil 1		VV					
3 5808034-0080	3/24/98/53	D Soil 1		V V					
4									
5									
6									
7									
Comments/Special Instructions:	Relinquished b (Signature)	PALO	To	Relinquished by (Signature)			elinquished b ignature)	oy:	
D. K. Turn	Printed Name:	4712 1M		Printed Name:		Pr	inted Name		
Quick Turn- annual time.		weston,	INC.	Company:		С	ompany:		
nesults by	Date: 3/26/4			Date:	Time:	D	ate:	Time:	
Monday?	Received by: (Signature)	1 R1161	1	Received by: (Signature)			eceived by: Signature)		
· MANUY.	Printed Name	Berg	in	<sup>,</sup> 'rinted Name:		Р	rinted Name	4	
	Company	PT J		Company:		C C	company:		
	Date:2/7/	ol 98 <sup>Time:</sup> 11	120	Date:	Time:		oate:	Time:	
Limits of Liability: ARI will perform all red	quested services in c	ccordance with ap	propriate i	methodology follov	ving Standard C	Operating Proce	dures and our	Quality Assurance Prog	gram. Ti

Limits of Liability: Aiki will perform direquested services in accordance will appropriate months of services, and services are defined and services and services are defined and services. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed program meets stondards for the industry. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed program meets stondards for the industry. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed the involved amount for said services. The acceptance by the client of a proposal for services by ARI releases ARI from any liability in excess thereof, not withstanding any provision to the contrary in any contract, purchase order or co-signed agreement between ARI and the client.



### TOTAL GASOLINE RANGE HYDROCARBONS WTPHG Range Toluene to C12 by GC/FID

QC Report No: V838-Boeing Plant II

Matrix: Soil

Project: 03709-034-410-0002-00

Data Release Aut rized: Dat

Date Received: 03,26/98

Reported: 04/02 3

Lab ID	Client Sample ID	Date Analyzed	Dilution Factor	Gas Range Hydrocarbons	Gasoline ID	Surr A Rec	Surr B Rec
V838-0330MB	Method Blank	03/30/98	1:1	5.0 U	NO	103.%	106.%
98-5776-V838A	SB08032-0060	03/30/98	1:1	6.2 U	NO	93.4%	87.3%
98-5777-V838B	SB08033-0055	03/30/98	1:1	5.6 U	NO	96.2%	95.7%
98-5778-V838C	SB08034-0080	03/30/98	1:1	5.8 U	NO	95.9%	95.0%

-pum
4/7/98

Surrogate A is Trifluorotoluene.

Surrogate B is Bromobenzene.

Values reported in ppm (mg/kg) on a dry weight basis.

Quantitation on total peaks in the gasoline range from Toluene to C12.

- U Compound not detected at the given detection limit.
- X Value detected above linear range of instrument. Dilution required.
- J Indicates an estimated value below the calculated detection limit.
- S No value reported due to saturation of the detector. Dilution required.
- D Indicates the surrogate was not detected because of dilution of the extract.
- NR Indicates no recovery due to matrix interference.



### TOTAL GASOLINE RANGE HYDROCARBONS WTPHg Range Toluene to C12 by GC/FID

Lab Sample ID: V838SB

QC Report No: V838-Boeing Plant II

LIMS ID: 98-5776

Project: 03709-034-410-0002-00

Matrix: Soil

Data Release Authorized:

Reported: 04/02/98

LABORATORY CONTROL SAMPLE RECOVERY REPORT Analyzed 03/30/98

CONSTITUENT	SPIKE FOUND	SPIKE ADDED	% RECOVERY
LABORATORY CONTROL SAMPLE		<b>3</b>	
Gasoline Range Hydrocarbons	2.48	2.5	99.2%

### TPHg Surrogate Recovery

Trifluorotoluene Bromobenzene

118%

NR

Values reported in parts per million (mg/kg)

TPHG SPIKE CONTROL LIMITS

Percent Recovery

80.0-120%

Advisory QA Limits

1/7/48



### Sample No: Method Blank

Lab Sample ID: V838MB

QC Report No: V838-Boeing Plant II

LIMS ID: 98-5776 Matrix: Soil

Project: 03709-034-410-0002-00

Date Sampled:

Date Received: NA

NA

Data Release Authorized:

Reported: 04/02/98

Date analyzed: 03/30/98 Percent Moisture: NA

Sample Amount: 0.050 g Equiv

Dilution Factor: 1

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value			
71-43-2	Benzene	່ 50 ປ			
108-88-3	Toluene	50 U			
100-41-4	Ethylbenzene	50 U			
	m,p-Xylene	50 U			
95-47-6	o-Xylene	50 U			

### BETX 8020 Surrogate Recovery

Trifluorotoluene 102% Bromobenzene 103%

Rum
4/7/88

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- Indicates no recovery due to interferences.



**ANALYTICAL RESOURCES INCORPORATED** 

Sample No: SB08032-0060

Lab Sample ID: V838A

LIMS ID: 98-5776

Matrix: Soil

QC Report No: V838-Boeing Plant II

Project:

03709-034-410-0002-00

Date Sampled: 03/26/98

Date Received: 03/26/98

Data Release Authorized:

Reported: 04/02/98

clt

Date analyzed: 03/30/98 Percent Moisture: 22.9% Sample Amount: 0.040 g

Dilution Factor: 1

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value			
71-43-2	Benzene	62 U			
108-88-3	Toluene	· 62 U			
100-41-4	Ethylbenzene	62 Ü			
	m,p-Xylene	100			
95-47-6	o-Xylene	62 U			

### BETX 8020 Surrogate Recovery

Trifluorotoluene 91.6% Bromobenzene 87.0%

R44 198

- Indicates compound was analyzed for, but not detected at the U given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Indicates a value above the linear range of the detector. Е Dilution Required
- Indicates no value reported due to saturation of the detector. S
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. Y The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- Indicates compound was not analyzed. NA
- NR Indicates no recovery due to interferences.



ANALYTICAL **RESOURCES** INCORPORATED

Sample No: SB08033-0055

Lab Sample ID: V838B

LIMS ID: 98-5777 Matrix: Soil

QC Report No: V838-Boeing Plant II

Project:

03709-034-410-0002-00

Date Sampled:

03/26/98

Date Received: 03/26/98

Data Release Authorized: Reported: 04/02/98

Date analyzed: 03/30/98 Percent Moisture: 13.4% Sample Amount: 0.045 g

Dilution Factor:

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	56	U
108-88-3	Toluene	56	U
100-41-4	Ethylbenzene	56	U
	m,p-Xylene	56	U
95-47-6	o-Xylene	56	U

### BETX 8020 Surrogate Recovery

95 5% Trifluorotoluene Bromobenzene 95.4%

- Indicates compound was analyzed for, but not detected at the U given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Indicates a value above the linear range of the detector. E Dilution Required
- Indicates no value reported due to saturation of the detector. S
- D Indicates the surrogate was diluted out.
- Found in associated method blank. В
- Indicates a raised reporting limit due to matrix interferences. Y The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- Indicates no recovery due to interferences.



ANALYTICAL **RESOURCES** INCORPORATED

Sample No: SB08034-0080

Lab Sample ID: V838C

LIMS ID: 98-5778

Matrix: Soil

OC Report No: V838-Boeing Plant II

Project: 03709-034-410-0002-00

Date Sampled: 03/26/98

Date Received: 03/26/98

Data Release Authorized: Clt

Reported: 04/02/98

Date analyzed: 03/30/98 Percent Moisture: 16.1%

Sample Amount: 0.043 g

Dilution Factor: 1

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	<u></u>	Value	
71-43-2	Benzene		58	Ū
108-88-3	Toluene		3 58	U
100-41-4	Ethylbenzene		58	U
	m,p-Xylene		58	U
95-47-6	o-Xylene		58	U

### BETX 8020 Surrogate Recovery

Trifluorotoluene 94.3% Bromobenzene 94.8%

17/98

- Indicates compound was analyzed for, but not detected at the IJ given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Indicates a value above the linear range of the detector. Е Dilution Required
- Indicates no value reported due to saturation of the detector. S
- Indicates the surrogate was diluted out. D
- В Found in associated method blank.
- Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



Sample No: SB08033-0055

Lab Sample ID: V838B

QC Report No: V838-Boeing Plant II

LIMS ID: 98-5777

Project: 03709-034-410-0002-00

Matrix: Soil

Date Received: 03/26/98

Data Release Authorized:

Reported: 04/02/98

4/1/18

MATRIX SPIKE/SPIKE DUPLICATE RECOVERY

Date Analyzed: 03/30/98

CONSTITUENT		MPLE VALUE	SPIKE FOUND	SPIKE ADDED	% RECOVERY	RPD
MATRIX SPIKE						
Benzene	<	55.6	2850	3230	88.2%	
Toluene	.<	55.6	2790	3230	86.4%	
Ethylbenzene	<	55.6	2810	3230	87.0%	
m,p-Xylene	<	55.6	5640	6450 <sub>.</sub>	87.4%	
o-Xylene	<	55.6	2800	3230	86.7%	
				<b>.</b>		
MATRIX SPIKE DUPLICATE						
Benzene	<		2890	3300	87.6%	0.7%
Toluene	<	55.6	2870	3300	87.0%	0.7%
Ethylbenzene	<	55.6	2870	3300	87.0%	0.0%
m,p-Xylene	<	55.6	5830	6600	88.3%	1.0%
o-Xylene	<	55.6	2870	3300	87.0%	0.4%
BETX SURROGATE RECOVER	ES	MATRIX	SPIKE	MATRIX SPIKE DUPI	ICATE	
Trifluorotoluene		97.9%		95.3%		
Bromobenzene		98.2%		94.6%		

Reported in Total ug/kg Dry Weight (ppb)

BETX SPIKE CONTROL LIMITS

Percent Recovery 75-130% Duplicate RPD <30%

Rum
4/7/18



### SOIL BETX SYSTEM MONITORING COMPOUND SUMMARY

Matrix: Soil

QC Report No: V838

LIMS ID	Lab ID	Client ID	TFT	BB	T	OT OU	<u>T</u>
		The second of the second of	102				
98-5776MB	033098MB	Method Blank	102%	103%	•	0	1 1
98-5776	V838A	SB08032-0060	92%	87%		0	
98-5777	V838B	SB08033-0055	96%	95%	200	Q	
98-5777	V838B-MS	SB08033-0055-MS	98%	98%	4.5	0	
98-5777	V838B-MSD	SB08033-0055-MSD	95%	95%		0	
98-5778	V838C	SB08034-0080	94%	95%		0	

		•	MB/LCS	SAMPLE
			QC LIMITS	QC LIMITS
(TFT)	=	Trifluorotoluene	(84-106)	(85-113)
(BB)	=	Bromobenzene	(82-110)	(68-121)

PMM 4/7/198

Limits Updated - 02/15/97

- \* Values outside of advisory QC limits
- D System Monitoring Compound diluted out

Page 1 for V838



### SOIL TPHG SYSTEM MONITORING COMPOUND SUMMARY

Matrix: Soil

QC Report No: V838

LIMS ID	Lab ID	Client ID	TFT	BB	TOT OUT
98-5776 <b>M</b> B	033098MB	Method Blank	103%	106%	0
98-5776LC	033098LC	Lab Control	118%	NR .	0
98-5776	V838A	SB08032-0060	93%	87%	0
98-5777	V838B	SB08033-0055	96%	96%	0
98-5778	V838C	SB08034-0080	96%	95%	0

1/3/98

Limits Updated - 02/15/97

# Column to be used to flag recovery values

D System Monitoring Compound diluted out

Page 1 for V838

## **Chain of Custody Record & Laboratory Analysis Request**

Page \_\_\_\_\_ of \_\_\_\_ Number of coolers: \_\_\_\_\_



Analytical Kesources, Incorporated Analytical Chemist and Consultants 400 Ninth Avenue North Seattle, WA 98109-4708 (206) 621-6490

ARI	Client: BOCING WG	10N	Phon	e#: 9	21-7	600	Rad.	Survey:						(206)	621-752	3 (Fax)	
Clie	nt Contact: R.BOLERS/	f. M	161NN	15					Anal	yvis Red	quired					otes/Com	
	nt Project ID: 03709-03				2-8		, er	46							980	933 8-99 W3:	to
San	plers: LOTTSFELOT	.6					\$ \$ \frac{1}{2} \f	W-TP146							9	Y-99	35
	Sample ID	Date	Time	Matx	No Cont	Lab ID	24	3								W3.	5/
1	58-08037-0080	5/18	1049	5	2		X	X									
2	4B-08036-0060		1052	5	2		X	X									
3	43-08035-9060	V	1054	5	2		X	X									
4																	
5																	
6	•		i i														
7					-												
ARI	Project No:	Relinqu (Signat	uished by: ure)	42	AW	relat	Rel	inquish gnature)	ed by:	·			Relir (Sigr	nquish nature)	ed by:		
Cor	nments/Special Instructions:	Printed	Name:	T5F1	ELD-	T	Pri	nted Na	me:				Print	ed Na	me:	- ,	
2	4 HR PAT	Compa	iny: WEG	101	1, I,	ر کار	Co	mpany:					Com	pany:			
		Date:	5-18-9	8 Tin	ne: 16	26	Da	te:		Tim	e: ,		Date	:		Time:	***************************************
<u></u>	ANHOLE EXCAVATION	5	ed by	J	2	$\overline{}$	Red (Sig	ceived b gnature)	y:			111	Rece (Sign	eived k nature)	oy:		
'س	ANHOLE EXCAVATION	Printec	Name:	>	tais	un	Pri	nted Na	me:				Print	ed Na	me:	:	
		Compa	any: Ap			-/	Со	mpany:					Com	pany:			
		Date:	5/18/	70 Tir	ne:16:	35	Da	te:		Tim	e:		Date	):		Time:	

Limits of Liability: ARI will perform all requested services in accordance with appropriate methodology following Standard Operating Procedures and our Quality Assurance Program. This program meets standards for the industry. The total liability of ARI, its officers, agents, employees, or successors, arising out of or in connection with the requested services, shall not exceed the invoiced amount for said services. The acceptance by the client of a proposal for services by ARI releases ARI from any liability in excess thereof, not withstanding any provision to the contrary in any contract, purchase order or co-signed agreement between ARI and the client.



### TOTAL GASOLINE RANGE HYDROCARBONS WTPHg Range Toluene to C12 by GC/FID

QC Report No:

W351-Boeing

Matrix: Soil

Bldg 2-80 Project:

03709-034-479-0001-00

Data Release Authorized: The Date Received:

05/18/98

Reported: 05/20/98

Lab ID	Client Sample ID	Date Analyzed	Dilution Factor	Gas Range Hydrocarbons	Gasoline ID	Surr A Rec	Surr B Rec
W351-0519MB	Method Blank	05/19/98	1:1	5.0 U	NO	91.8%	80.8%
98-9933-W351A	SB-08037-0080	05/19/98	1:1	130	NO	97.7%	92.8%
98-9934-W351B	SB-08036-0060	05/19/98	1:1	5.3 U	NO	92.5%	85.8%
98-9935-W351C	SB-08035-0060	05/19/98	1:1	5.3 U	NO	91.2%	82.8%

Surrogate A is Trifluorotoluene. Surrogate B is Bromobenzene.

Values reported in ppm (mg/kg) on a dry weight basis.

Quantitation on total peaks in the gasoline range from Toluene to C12.

- Compound not detected at the given detection limit. U
- Value detected above linear range of instrument. Dilution required. X
- Indicates an estimated value below the calculated detection limit. J
- No value reported due to saturation of the detector. Dilution required. S
- Indicates the surrogate was not detected because of dilution of the extract. D
- NR Indicates no recovery due to matrix interference.



### SOIL TPHG SYSTEM MONITORING COMPOUND SUMMARY

Matrix: Soil CH QC Report No: W351

LIMS ID	Lab ID	Client ID	TFT	ВВ	TOT OUT
98-9933MB	051998MB	Method Blank	92%	81%	0
98-9933	W351A	SB-08037-0080	98%	93%	0
98-9934	W351B	SB-08036-0060	92%	86%	0
98-9935	W351C	SB-08035-0060	91%	83%	0

	MB/LCS	SAMPLE
	QC LIMITS	QC LIMITS
= Trifluorotoluene	(58-151)	(30-160)
= Bromobenzene	(36-160)	(30-160)
	= Trifluorotoluene = Bromobenzene	= Trifluorotoluene (58-151)

Limits Updated - 02/15/97

# Column to be used to flag recovery values

D System Monitoring Compound diluted out

Page 1 for W351



ANALYTICAL RESOURCES **INCORPORATED** 

Sample No: SB-08035-0060

Lab Sample ID: W351C

LIMS ID: 98-9935

Matrix: Soil

QC Report No:

W351-Boeing

Project:

Bldg 2-80 03709-034-470-0001-00

Date Sampled:

05/18/98

Date Received:

05/18/99

Data Release Authorized: 64

Reported: 05/20/98

Sample Amount: 0.047 g

Dilution Factor: 1

Date analyzed: 05/19/98 Percent Moisture: 6.4%

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value
71-43-2	Benzene	53 U
108-88-3	Toluene	53 U
100-41-4	Ethylbenzene	53 U
	m,p-Xylene	53 U
95-47-6	o-Xylene	53 U

### BETX 8020 Surrogate Recovery

Trifluorotoluene 96.9% Bromobenzene 85.9%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- Indicates an estimated value when that result is less than the J calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- Indicates compound was not analyzed. NA
- Indicates no recovery due to interferences.

### ORGANICS ANALYSIS DATA SHEET BETX by Method 8020



Sample No: SB-08036-0060

Lab Sample ID: W351B

LIMS ID: 98-9934

Matrix: Soil

QC Report No: W351-Boeing

Project: Bldg 2-80

03709-034-470-0001-00

Date Sampled:

05/18/98

Date Received: 05/18/98

Data Release Authorized: 5/L3/41

Reported: 05/20/98

Date analyzed: 05/19/98

Percent Moisture: 7.4%

Sample Amount: 0.047 g

Dilution Factor:

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	 Value	
71-43-2	Benzene	53	U
108-88-3	Toluene	53	U
100-41-4	Ethylbenzene	53	U
	m,p-Xylene	120	
95-47-6	o-Xylene	53	U

### BETX 8020 Surrogate Recovery

Trifluorotoluene 101% Bromobenzene 89.0%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- Е Indicates a value above the linear range of the detector. Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- В Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



ANALYTICAL RESOURCES INCORPORATED

Sample No: SB-08037-0080

Lab Sample ID: W351A

LIMS ID: 98-9933

Matrix: Soil

QC Report No: W351-Boeing

Project: Bldg 2-80

03709-034-470-0001-00

Date Sampled: 05/18/98
Date Received: 05/18/98

Data Release Authorized: 4

Reported: 05/20/98

5/20/97

Date analyzed: 05/19/98 Percent Moisture: 30.8% Sample Amount: 0.035 g

Dilution Factor: 1

### Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value	
71-43-2	Benzene	71	U
108-88-3	Toluene	71	U
100-41-4	Ethylbenzene	2,200	
	m,p-Xylene	1,800	
95-47-6	o-Xylene	810	

### BETX 8020 Surrogate Recovery

Trifluorotoluene 104% Bromobenzene 94.9%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- E Indicates a value above the linear range of the detector.
  Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- B Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences. The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



### Sample No: Method Blank

Lab Sample ID: W351MB

QC Report No:

W351-Boeing

LIMS ID: 98-9933 Matrix: Soil Project: Bldg 2-80

03709-034-470-0001-00

Date Sampled:

Date Received: NA

NA

Data Release Authorized: cu

Reported: 05/20/98

Date analyzed: 05/19/98

Percent Moisture: NA

Sample Amount: 0.050 g Equiv

Dilution Factor: 1

Reported in Total ug/kg Dry Weight

CAS Number	Analyte	Value
71-43-2	Benzene	50 U
108-88-3	Toluene	50 U
100-41-4	Ethylbenzene	50 U
	m,p-Xylene	50 U
95-47-6	o-Xylene	50 U

### BETX 8020 Surrogate Recovery

Trifluorotoluene 98.9% Bromobenzene 86.0%

- U Indicates compound was analyzed for, but not detected at the given detection limit.
- J Indicates an estimated value when that result is less than the calculated detection limit.
- E Indicates a value above the linear range of the detector.
  Dilution Required
- S Indicates no value reported due to saturation of the detector.
- D Indicates the surrogate was diluted out.
- B Found in associated method blank.
- Y Indicates a raised reporting limit due to matrix interferences.

  The analyte may be present at or below the listed concentration, but in the opinion of the analyst, confirmation was inadequate.
- NA Indicates compound was not analyzed.
- NR Indicates no recovery due to interferences.



Lab Sample ID: W351SB

LIMS ID: 98-9933

Matrix: Soil

QC Report No: W351-Boeing

Project: Bldg 2-80

03709-034-470-0001-00

Data Release Authorized: ch

Reported: 05/20/98

LABORATORY CONTROL SAMPLE

Date analyzed: 05/19/98

	SPIKE	SPIKE	%
CONSTITUENT	FOUND	ADDED	RECOVERY
Benzene	25.5	25.0	102%
Toluene	25.8	25.0	103%
Ethylbenzene	24.8	25.0	99.2%
m,p-Xylene	51.0	50.0	102%
o-Xylene	24.9	25.0	99.6%

### BETX SURROGATE RECOVERIES

102 % Trifluorotoluene Bromobenzene 89.2%

Reported in Total ug/kg Dry Weight (ppb)

BETX SPIKE CONTROL LIMITS

Percent Recovery 75-130%



### SOIL BETX SYSTEM MONITORING COMPOUND SUMMARY

Matrix: Soil

ch Slr-190

QC Report No: W351

LIMS ID	Lab ID	Client ID	TFT	ВВ	TOT OUT
98-9933 <b>M</b> B	051998MB	Method Blank	99%	86%	o
98-9933LC	051998LC	Lab Control	102%	89%	0
98-9933	W351A	SB-08037-0080	104%	95%	0
98-9934	W351B	SB-08036-0060	101%	89%	0
98-9935	W351C	SB-08035-0060	97%	86%	0

	MB/LCS	SAMPLE
	QC LIMITS	QC LIMITS
(TFT) = Trifluorotoluene	(84-106)	(85-113)
(BB) = Bromobenzene	(82-110)	(68-121)

Limits Updated - 02/15/97

- Values outside of advisory QC limits
- System Monitoring Compound diluted out

Page 1 for W351

# APPENDIX C STOCKPILED SOIL SAMPLING DATA

ENVIRONM AL ANALYSIS LABORATORY Boeing Commercial Airplane Group P O Box 3707, MS 72-04 Seattle, WA 98124-2207

X-27775C ORIG. 11/96

	(	,	4
PAGE	 UF		

#### Ph. 237-1051 CHAIN OF CUSTODY RECORD/LABORATORY ANALYSIS REQUEST IShadica was an a sample house a superational state of the superations MALSTOP 19-16 CHARGELBJE/CONTROL MUMBER MAIL STOP Mike Gleson Rich Strin (washer) SAMPLE DESCRIPTION AND LOCATION SAMP COLL TIME MATX ANALYSIS REQUESTED (Use codes on back to indicate tests.) 1. PLZSA- 139Z 1125 Tot Melok, Tot. VOA, Semi VOA, TPH, PCB 4 2 PLZSA - 1393 1630 3. PLZ SA- 1394 1135 4. PLZSA- 1395 1140 6 5. PLZSA- 1396 1145 6 6. PLZSA - 1397 1150 7. STO TAT 9, 10. Comments/Special Instructions Soil Stock piles from OA3 Intern Measure Stockple 1 - Press - 1773 1799 **Retinevished by** (SIGNATURE) (SIGNATURE) Printed Name Yirsted Marie Time Received by Received by Minted Marie Lisa Gaul Printed Name 1397 Dete Time 3:30 Dete Time

	Commen(s	106 521-76C  Temphone No.		Location	12 Chica	LAYKY VOINSE OW		rax Leader	The Boeing Company	04. 16. 96 11:50 AM *BOFI
Distriction	1202 ST COT	- [	Lucation	Cox/um	Company	Trom Lines	39/9/16	No. of Pages		*WOMING Minuteman
7	425 118-100		Bldg. No.		1/2	Maliston	C O'Gn. No.	1		FO1

### HAZARDOUS WASTE REPORT

Lab Id: 98-8230 Field Id No.: PL28A-1392

Analyte	Result	Units	Method #	Analyst	Date	Status
PCB:	< 0.05		4			· · · · · · · · · · · · · · · · · · ·
Total Pet. Hydrocarbo:	23.00	ppm	8080	KSC	4/ 2/98	
Arsenic:	1.84	ppm	418.1	Mike	4/ 1/98	
Barium:	17.75	mg/Kg	200.7	Paula	4/ 1/98	
Cadmium:	The state of the s	mg/Kg	200.7	Paula	4/ 1/98	
	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	y
Chromium	11.50	mg/Kg	200.7	Paula	4/ 1/98	- -
Copper	12.85	mg/Kg	200.7	Paula -	4/ 1/98	
Lead:	4.46	mg/Kg	200.7	Paula	4/ 1/98	
<b>Me</b> raury:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Nickeli	7.90	mg/Kg	200.7	Paula	4/ 1/98	
Selenium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
silver	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Zinc:	20.83	mg/Kg	200.7	Paula	4/ 1/98	
Irons	9371.00	mg/Kg	200.7	Paula	4/ 1/98	
Calcium:	3707.00	mg/Kg	200.7	Paula	4/ 1/98	
Thallium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Bodiuma	698.10	mg/Kg	200.7	Paula	4/ 1/98	
Magnesium:	2038.00	mg/Kg	200.7	Paula	4/ 1/98	
Aluminum	8285.00	mg/Kg	200.7	Paula	4/ 1/98	
Manganese:	79.87	mg/Kg	200.7	Paula	4/ 1/98	
Beryllium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Cobalte	4.84	mg/Kg	200.7	Paula	4/ 1/98	
Bismuth:	10.84	mg/Kg	200.7	Paula	4/ 1/98	
Vanadium:	26.55	mg/Kg	200.7	Paula	4/ 1/98	
Bensene:	< 10	ppb	602/624	Ed	4/ 1/98	
Toluene	< 10	ppb	602/624	Ed	4/ 1/98	
Ethylbenzene	< 10	ppb	602/624	Ed	4/ 1/98	
Methylene Chloride:	< 10	ppb	601/624	Ed	4/ 1/98	
1,1 Dichlorosthans:	< 10	ppb	601/624	Ed	4/ 1/98	
Chloroforms	< 10	ppb	601/624	Ed	4/ 1/98	
1,1,1 Trichloroethane:	< 10	ppb	601/624	Ed	4/ 1/98	
Trichloroethene:	< 10	dqq	601/624	Ed	4/ 1/98	
Tetrachloroethene:	< 10	dqq	601/624	Ed	4/ 1/98	
1,1,2,2 Tetrachloroet:	< 10	ppb	601/624	Ed	4/ 1/98	
Acetone:	< 100	ppb	602	Ed	4/ 1/98	
o-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	
m&p-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	

Report prepared by: Asa Saul Date: 4/2/98

### HAZARDOUS WASTE REPORT

Lab Id: 98-B231 Field Id No.: PL28A-1393

ld Notes: Stock pile 1 Analyte	Result	Units	Method #	Analyst	Date	Status
PCB	1,5144	سرخ	8080	KSC	4/ 2/98	
Total Pet. Hydrocarbo:		ppm	418.1	Mike	4/ 1/98	
Arsenic		mg/Kg	200.7	Paula	4/ 1/98	
Barium	31.80	mg/Kg	200.7	Paula	4/ 1/98	
Cadmiums		mg/Kg	200.7	Paula	4/ 1/98	
Chromium		mg/Kg	200.7	Paula	4/ 1/98	
Copper		mg/Kg	200.7	Paula	4/ 1/98	
Lead:		mg/Kg	200.7	Paula	4/ 1/98	
Mercury		mg/Kg	200.7	Paula	4/ 1/98	
Nickel:		mg/Kg	200.7	Paula	4/ 1/98	
Selenium:		mg/Kg	200.7	Paula	4/ 1/98	
Silver	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Zinc:		mg/Kg	200.7	Paula	4/ 1/98	
Iron:	11970.0	mg/Kg	200.7	Paula	4/ 1/98	
Calcium:	4554.00	mg/Kg	200.7	Paula	4/ 1/98	
Thallium:	< 0.05	mg/Kg	200.7	Paula		
Sodium:	522.30	mg/Kg	200.7	Paula	4/ 1/98	
Magnesium:	2776.00	mg/Kg	200.7	Paula	4/ 1/98	
Aluminum:	8915.00	mg/Kg	200.7	Paula	4/ 1/98	
Manganese:	150.50	mg/Kg	200.7	Paula	4/ 1/98	
Beryllium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Cobalt:	7.34	mg/Kg	200.7	Paula	4/ 1/98	
Bismuth:	12,42	mg/Kg	200.7		4/ 1/98	
Vanadiums	33.88	mg/Kg	200.7	Paula	4/ 1/98	
Benzene:	< 10	bbp må\vd	602/624	Paula	4/ 1/98	
Toluene:	< 10	ppb	602/624	Ed .	4/ 1/98	
Ethylbenzene:	< 10		•	<b>E</b> d	4/ 1/98	
Methylene Chloride:	< 10	pp pg	602/624	Ed	4/ 1/98	
1,1 Dichlorosthans:	< 10	ppb	601/624	Ed	4/ 1/98	
Chloroform:	< 10	ppb	601/624	Ed	4/ 1/98	
1,1,1 Trichloroethane:	< 10	dqq	601/624	Ed	4/ 1/98	
Trichloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
Tetrachloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
1,1,2,2 Tetrachloroet:	< 10	ppb	601/624	Ed	4/ 1/98	
Agetone:		ppb	601/624	Ed	4/ 1/98	
o-Xylene:	< 100	ppb	602	Ed	4/ 1/98	
	< 10	ppb	602/624	ed	4/ 1/98	
m&p-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	

Report prepared by:

Date: 4/ 2/98

Report approved by Almda

4/2/98

### HAZARDOUS WASTE REPORT

Lab Id: 98-B232 Field Id No.: PL2SA-1394

Analyte	Result	Units	Method #	Analyst	Date	Statu
<ul> <li>Wight State (Artist Medical Property)</li> </ul>						
PCB:	< 0.05	ppm	8080	Kec	4/ 2/98	
Total Pat. Hydrocarbo:	81.00	<b>bb</b> w	418.1	Nike	4/ 1/98	
Arsenica	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	•
Barium:	28.45	mg/Kg	200.7	Paula	4/ 1/98	
Cadmium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Chromium:	15.43	mg/Kg	200.7	Paula	4/ 1/98	
Coppers	12.63	mg/Kg	200.7	Paula	4/ 1/98	
Lead:	16.15	mg/Kg	200.7	Paula	4/ 1/98	
Mercury	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Nickel:	11.80	mg/Kg	200.7	Paula	4/ 1/98	
Selenium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Silver:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Zinc:	60.88	mg/Kg	200.7	Paula	4/ 1/98	
Ironi	11310.0	mg/Kg	200.7	Paula	4/ 1/98	
Calcium	4449.00	mg/Kg	200.7	Paula	4/ 1/98	
Thallium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Sodiumi	682.30	mg/Kg	200.7	Paula	4/ 1/98	
Magnesium:	2413.00	ng/Kg	200.7	Paula	4/ 1/98	
Aluminum:	9194.00	mg/Kg	200.7	Paula	4/ 1/98	
Manganese:	129.90	mg/Kg	200.7	Paula	4/ 1/98	
Beryllium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Cobalt:	6.44	mg/Kg	200.7	Paula	4/ 1/98	
Bismuths	14.42	mg/Kg	200.7	Paula	4/ 1/98	
Vanadium:	34.37	mg/Kg	200.7	Paula	4/ 1/98	
Benzane:	< 10	dqq	602/624	Ed	4/ 1/98	
Toluene:	< 10	ppb	602/624	Ed	4/ 1/98	
Ethylbenzene:	< 10	ppb	602/624	Ed	4/ 1/98	
Methylene Chloride:	< 10	dqq	601/624	Ed	4/ 1/98	
1,1 Dichloroethane:	< 10	ppb	601/624	Ed	4/ 1/98	
Chloroforms	< 10	dqq	601/624	Ed	4/ 1/98	
1,1,1 Trichlorcethane:	< 10	ppb	601/624	Ed	4/ 1/98	
Trichloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
Tetrachloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
1,1,2,2 Tetrachloroet:	< 10	ppb	601/624	Ed	4/ 1/98	
Acetone:	< 100	ppb	602	Ed	4/ 1/98	
o-Xylene;	< 10	ppb	602/624	Ed	4/ 1/98	
m&p-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	

Report prepared by: June Date: 4/2/98
Report approved by: Linda Chicquette Date: 4/2/98

### HAZARDOUS WASTE REPORT

Lab Id: 98-8233 Field Id No.: PL2SA-1395

DCOCK DIIE /	F:	leld	Notes:	Stock	nile	2
--------------	----	------	--------	-------	------	---

lid Notes: Stock pile 2 Analyte	Result	Units	Method #	Analyst	Date	Status
		~~**		~~~~		
PCB:	< 0.05	ppm	8080	KSC	4/ 2/98	
Total Pet. Hydrocarbo:	46.00	ppm	418.1	Kike	4/ 1/98	
Arsenica	-1.04	mg/Kg	200.7	Paula	4/ 1/98	
Barium:	20.94	mg/Kg	200.7	Paula	4/ 1/98	
Cadmium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Chromium:	13.15	mg/Kg	200.7	Paula	4/ 1/98	
Coppers	15.08	mg/Kg	200.7	Paula	4/ 1/98	
Lead:	7.54	mg/Kg	200.7	Paula	4/ 1/98	
Mercury:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Nickel:	9.10	mg/Kg	200.7	Paula	4/ 1/98	
Selenium;	2.36	mg/Kg	200.7	Paula	4/ 1/98	
Silver:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Zinc:	39.11	mg/Kg	200.7	Paula	4/ 1/98	
iron:	9947.00	mg/Kg	200.7	Paula	4/ 1/98	
Calcium:	3867.00	mg/Kg	200.7	Paula	4/ 1/98	
Thallium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Sodium:	691.00	mg/Kg	200.7	Paula	4/ 1/98	
Magnesium:	2041.00	mg/Kg	200.7	Paula	4/ 1/98	
Aluminum:	8265.00	mg/Kg	200.7	Paula	4/ 1/98	
Manganese:	86.90	mg/Kg	200.7	Paula	4/ 1/98	
Beryllium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Cobalt:	5.19	mg/Kg	200.7	Paula	4/ 1/98	
Bismuth:	6.16	mg/Kg	200.7	Paula	4/ 1/98	
Vanadium:	32.56	mg/Kg	200.7	Paula	4/ 1/98	
Benzene:	< 10	ppb	602/624	Ed	4/ 1/98	
Toluene:	< 10	ppb	602/624	Ed	4/ 1/98	
Ethylbenzene:	< 10	ppb	602/624	Ed	4/ 1/98	
Methylene Chloride:	< 10	dag	601/624	Ed	4/ 1/98	
1,1 Dichloroethane:	< 10	ppb	601/624	Ed	4/ 1/98	
Chloroform:	< 10	dqq;	601/624	Ed		
1,1,1 Trichloroethane:	< 10	dqq	601/624	Ed Ed	4/ 1/98	
Trichloroethene:	< 10	<sup>i</sup> ppb	601/624	Ed	4/ 1/98	
Tetrachloroethene:	< 10	qqq	601/624	Ed .	4/ 1/98	
1,1,2,2 Tetrachlorost:	< 10	ppb	601/624		4/ 1/98	
Acetone:	< 100	ppp ppp	602	Ed wa	4/ 1/98	
o-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	
m&p-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	
	7 44	PV	UU4/ 044	Ed	4/ 1/98	

Report prepared by: Linda Chicquette Date: 4/2/

Page:

### HAZARDOUS WASTE REPORT

Lab 1d: 98-B234 Field Id No.: PL28A-1396

< 0.05 44.00 < 0.05 21.80 < 0.01 11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05 739.50	ppm mg/Kg	8080 418.1 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	KSC Mike Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 2/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
44.00 < 0.05 21.80 < 0.01 11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	ppm mg/Kg	418.1 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Mike Paula	4/ 1/98 4/ 1/98	
< 0.05 21.80 < 0.01 11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98	
21.80 < 0.01 11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98	
< 0.01 11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98	
11.98 10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98	
10.37 11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
11.38 < 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
< 0.05 8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
8.16 < 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
< 0.05 < 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
< 0.01 39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7 200.7	Paula Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
39.02 9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7 200.7	Paula Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98 4/ 1/98	
9986.00 3863.00 < 0.05	mg/Kg mg/Kg mg/Kg mg/Kg	200.7 200.7 200.7	Paula Paula Paula	4/ 1/98 4/ 1/98 4/ 1/98	
3863.00 < 0.05	mg/Kg mg/Kg mg/Kg	200.7 200.7	Paula Paula	4/ 1/98 4/ 1/98	
< 0.05	mg/Kg mg/Kg	200.7	Paula	4/ 1/98	
	mg/Kg				
				a, 1/09	
	mg/Kg	200.7	Paula	4/ 1/98	
1922.00	mg/Kg	200.7	Paula	4/ 1/98	
8148.00	mg/Kg	200.7	Paŭla	4/ 1/98	
85.08	mg/Kg	200.7	Paula	4/ 1/98	
< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
5.22	mg/Kg	200.7	Paula	4/ 1/98	
5.52	mg/Kg	200.7	Paula	4/ 1/98	
31.32	mg/Kg	200.7	Paula	4/ 1/98	
< 10	ppb	602/624	Ed	4/ 1/98	
< 10	ppb	602/624	Ed	4/ 1/98	
< 10	ppb	602/624	Ed	4/ 1/98	
< 10	ppb	601/624	Ed	4/ 1/98	
< 10	ppb	601/624			
		•		7	
		•			
		•			
	-	•			
		•			
- TAN :				• •	
		UUZ/ QZ4	· ·		
	< 10 < 10 < 10 < 10 < 10 < 10	< 10 ppb < 10 ppb < 10 ppb < 10 ppb < 10 ppb	< 10 ppb 601/624 < 100 ppb 602 < 10 ppb 602/624	<pre>&lt; 10     ppb     601/624     Ed &lt; 100     ppb     602      Ed &lt; 10     ppb     602/624     Ed</pre>	<pre>&lt; 10     ppb     601/624     Ed     4/ 1/98 &lt; 100     ppb     602     Ed     4/ 1/98</pre>

Report prepared by:

Report approved by Linda Chiquetto Date: 4/2

### HAZARDOUS WASTE REPORT

Lab Id: 98-8235 Field Id No.: PL28A-1397

Analyte	Result	Units	Method #	Analyst	Date	Status
· · · · · · · · · · · · · · · · · · ·		** *** *** *** *** ***				
PCB:	< 0.05	ppm	8080	KSC	4/ 2/98	
Total Pet. Hydrocarbo:	623.00	ppm	418.1	Mike	4/ 1/98	
Arsenica	1.64	mg/Kg	200.7	Paula	4/ 1/98	
Barium:	22.83	mg/Kg	200.7	Paula	4/ 1/98	
Cadmium:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Chromium:	11.82	mg/Kg	200.7	Paula	4/ 1/98	
Copper:	12.25	mg/Kg	200.7	Paula	4/ 1/98	
Lead:	20.15	mg/Kg	200.7	Paula	4/ 1/98	
Mercury:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Nickel:	9.13	mg/Kg	200.7	Paula	4/ 1/98	
Selenium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Silver:	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Zinc:	216.90	mg/Kg	200.7	Paula	4/ 1/98	
Iron:	9819.00	mg/Kg	200.7	Paula	4/ 1/98	
Calcium:	3885.00	mg/Kg	200.7	Paula	4/ 1/98	
Thallium:	< 0.05	mg/Kg	200.7	Paula	4/ 1/98	
Sodium:	616.30	mg/Kg	200.7	Paula	4/ 1/98	
Magnesium:	1846.00	mg/Kg	200.7	Paula	4/ 1/98	
Aluminum:	7482.00	mg/Kg	200.7	Paula	4/ 1/98	
Manganese:	88.79	mg/Kg	200.7	Paula	4/ 1/98	
<b>Baryllium:</b>	< 0.01	mg/Kg	200.7	Paula	4/ 1/98	
Cobalt:	5.52	mg/Kg	200.7	Paula	4/ 1/98	
Bismuth:	11.40	mg/Kg	200.7	Paula	4/ 1/98	
Vanadium:	32.16	mg/Kg	200.7	Paula	4/ 1/98	
Bensene:	< 10	ppb	602/624	Ed	4/ 1/98	
Toluene:	< 10	ppb	602/624	Ed	4/ 1/98	
Ethylbenzene:	< 10	ppb	602/624	Ed	4/ 1/98	
Methylene Chloride:	< 10	ppb	601/624	Ed	4/ 1/98	
1,1 Dichloroethane:	< 10	ppb	601/624	Ed	4/ 1/98	
Chloroform:	< 10	ppb	601/624	Ed	4/ 1/98	
,1,1 Trichloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
Trichloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
Tetrachloroethene:	< 10	ppb	601/624	Ed	4/ 1/98	
,1,2,2 Tetrachloroet:	< 10	ppb	601/624	Ed	4/ 1/98	
Acetone:	< 100	· ppb	602	Ed.	4/ 1/98	
o-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	
m&p-Xylene:	< 10	ppb	602/624	Ed	4/ 1/98	

Report prepared by:

Dates 4/ 2/00

Report approved by:

Q Date:

**76** :

1

				10-	- (	pull	7	70	1/0	9-6	V 1 6	7				*****					<u>ر</u>	' ,	<u>()</u>				V	1 ر	/				<del>,</del>
BCAG FACILIT	TIES	EN	IVIF IGII	RON	MM ER	N(	ΠA 3	\L				'ON 'ION	C	НА	IN-	Ol	F-C	US	TC	DY	R	EC	OF	RD	AN	D	AN	ALY	'SIS	REC	QUE	EST	,
Requested						Р	hone	#:		344	(					4	\N	AL	Υ:	SIS	R	E(	טג	ES	T	<del></del>	-1	1	от	HER		PECIA	
Address:			·	. 4			ΑΧ#: 				· · ·	·		(\$1.08/	8.1)																		
Project Nur	mber:	и				Р	roje¢	t No	ime:	· .				(602/3020/8015)	one (4)									25		Metols	5)				( hr.)	days)	
Project Loc	043 I1					S	اطشها	er S	Signo	ture:				չեղթ (50	drocar		( <del>+</del> 13.		6. jps.		CBe Only			35.3)							SERVICE (24	£ (2-4	
Sample	Lab #		mount	M	atrix			etho		Sa	amp	ling	(8020)	ds Gask	Ferm H		Gredse	940	010	3020	3050-P(	3240	3270	NOE (3	S	20.00	E MATTE	(+20.2)				SERVIC	FAX
ID	(Lab use only)	# CONTAINERS	Volume/Amount	WATER	SLUDGE	OTHER	HNO	ICE	NONE	L	DAIL	TIME	BIEX (602/8020)	ΒΤΕΧ/ΤΡΗ ας Gasoline	Total Petroleum Hydrocomons (4 18.1)	74 (180.1)	Total Oil & Gredse (4.13.1)	FPA 604 /8040	EPA 601/8010	EPA 602/8020	EPA 608/8050-PCBe	EPA 624/8240	EPA 625/8270	TOTAL CYANIDE (335.	TC ORGANICS	FOA - Princin Pollutont	SETTLEABLE MATTER	PHENOLS (+20.2)			PRIORITY ONE	EXPEDITED SERVICE (2-4 days)	VERBALS/FAX
PL254-1	342	1		3	K			X		7,	3498												X			(							
DIZSA -13	l .	1			-\ -		+	X	-	3/3	1,	10 m						+				ex.	X	+		+	-						
A25A - 13		1			<u> </u>			X		17.	iks	1						+			a		X		+	+	-						H
1324-13	- 1	1	11 11		X			X		77,	sikes										5,50		K										
7251-13 P1251-13	%7	1			X			X		3/	3/4)			<b> </b>		-	+						X		140							-	
											134 b																						
25	shed by:				Dot	981	93	5	<u>J.</u>	- 4	by:	non		<u> </u>					lote #		4.	ei	(2	76		- //	154	<u>l</u>			1	<u></u>	1
Relinqui	ished by:	igin eerin	g M/S (	27-0}	Dat	e l	Tim	e I	-1}	د سرا،	( y	Labo	$2\gamma$	4/	14		r 16								nager				ar		R	EJRO	35.4



### SOIL SEMIVOLATILE SURROGATE RECOVERY SUMMARY

Matrix: Soil

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 DA3IM

Client ID	NBZ	FBP	TPH	PHL	2FP	TBP	2CP -	DCB	TOT OUT
Method Blank	64.4%	74.0%	65.1%	71.6%	67.4%	66.3%	74.9%	20.48	
Spike Blank	73.6%	74.2%	68.2%	75.2%	66.7%	69.5%	72.8%	79.4% 75.6%	0
PL25A-1392	79.4%	76.1%	81.8%	73.0%	72.0%	85.4%	66.1%	75.0%	0
PL25A-1393	75.4%	74.8%	87.2%	70.7%	61.4%	86.3%	67.0%	78.0%	.0
PL25A-1394	73.44	71.4%	88.5%	65.3₹	61.3%	80.0%	63.0%	67.8%	Q
PL25A-1395	75.0%	69.8%	83.6%	71.1%	69.8∜	92.8%	61.8%	67.1%	0
PL25A-1396 PL25A-1397	74.8%	73.3%	85.1%	69.3%	64.3%	93.3%	64.4%	71.6%	0
PL25A-1397	76.8%	76.6%	80.3%	79.6₹	68.0¥	92.9%	70.3%	78.8%	0

		LCS/MB LIMITS	QC LIMITS
(NBZ)	= Nitrobenzene-d5	(50-150)	(50-150)
(FBP)	= 2-Fluorobiphenyl	(50-150)	(50-150)
(TPH)	= p-Terphenyl-d14	(50-150)	(50-150)
(PHL)	= Phenol-d5	(50-150)	(50-150)
(2FP)	= 2-Fluorophenol	(50-150)	(50-150)
	= 2,4,6-Tribromophenol	(50-150)	(50-150)
	= 2-Chlorophenol-d4	(50-150)	(50-150)
(DCB)	<ul> <li>1,2-Dichlorobenzene-d4</li> </ul>	(50-150)	(50-150)

- # Column to be used to flag recovery values
- Values outside of required QC limits
- D Surrogate Compound diluted out



ORGANICS ANALYSIS DATA SHEET

Semivolatiles by GC/MS

Page 1 of 2

Lab Sample ID: V897A

LIMS ID: 98-6419

Matrix: Soil Data Release Authorized: ANS

Reported: 04/13/98

Sample No: PL25A-1392

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8 GPC Cleanup: NO

Sample Amount: 24.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: 20.4%

pH: 7.0

CAS Number	Analyte	ug/kg
108-95-2	Phenol	170 U
111-44-4	Bis-(2-Chloroethyl) Ether	170 U
95-57-8	2-Chlorophenol	83 U
541-73-1	1,3-Dichlorobenzene	83 U
106-46-7	1,4-Dichlorobenzene	83 U
100-51-6	Benzyl Alcohol	420 U
95-50-1	1,2-Dichlorobenzene	83 U
95-48-7	2-Methylphenol	170 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	83 U
106-44-5	4-Methylphenol	83 U
621-64-7	N-Nitroso-Di-N-Propylamine	170 U
67-72-1	Hexachloroethane	170 U
98-95-3	Nitrobenzene	83 U
78-59-1	Isophorone	83 U
88-75-5	2-Nicrophenol	420 U
105-67-9	2,4-Dimethylphenol	250 U
65-85-0	Benzoic Acid	830 U
111-91-1	bis(2-Chloroethoxy) Methane	83 U
120-83-2	2,4-Dichlorophenol	250 U
120-82-1	1,2,4-Trichlorobenzene	83 U
91-20-3	Naphthalene	83 U
106-47-8	4-Chloroaniline	250 U
87-68-3	Hexachlorobutadiene	170 U
59-50-7	4-Chloro-3-methylphenol	170 U
91-57-6	2-Methylnaphthalene	83 U
77-47-4	Hexachlorocyclopentadiene	420 U
B8-06-2	2,4,6-Trichlorophenol	420 U
95-95-4	2,4,5-Trichlorophenol	420 U
91-58-7	2-Chloronaphthalene	83 U
88-74-4	2-Nitroaniline	420 U
131-11-3	Dimethylphthalate	83 U
208-96-B	Acenaphthylene	83 U
99-09-2	3-Nitroaniline	500 U
83-32-9	Acenaphthene	83 U
51-28-5	2,4-Dinitrophenol	830 U
100-02-7	4-Nitrophenol	420 U
132-64-9	Dibenzofuran	83 U
606-20-2	2,6-Dinitrotolucne	420 U



### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897A

LIMS ID: 98-6419

Matrix: Soil

Data Release Authorized: PAD

Reported: 04/13/98

Sample No: PL25A-1392

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8
GPC Cleanup: NO

Sample Amount: 24.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1
Percent Moisture: 20.4%

pH: 7.0

CAS Number	Analyte	110 /lea
121-14-2	2,4-Dinitrotoluene	<u>ug/kg</u> 420 U
84-66-2	Diethylphthalate	83 U
7005-72-3	4-Chlorophenyl-phenylether	83 U
86-73-7	Fluorene	83 U
100-01-6	4-Nitroaniline	420 U
534-52-1	4,6-Dinitro-2-Methylphenol	830 U
86-30-6	N-Nitrosodiphenylamine	83 U
101-55-3	4-Bromophenyl-phenylether	83 U
118-74-1	Hexachlorobenzene	83 U
87 <b>-</b> 86-5	Pentachlorophenol	420 U
85-01-8	Phenanthrene	83 U
86-74-8	Carbazole	83 U
120-12-7	Anthracene	83 U
84-74-2	Di-n-Butylphthalate	83 U
206-44-0	Fluoranthene	83 U
129-00-0	Pyrene	83 U
85-68-7	Butylbenzylphthalate	83 U
91-94-1	3,3'-Dichlorobenzidine	420 U
56-55-3	Benzo(a)anthracene	83 U
117-81-7	bis(2-Ethylhexyl)phthalate	83 U
218-01-9	Chrysene	83 U
117-84-0	Di-n-Octyl phthalate	83 U
205-99-2	Benzo(b) fluoranthene	83 U
207-08-9	Benzo(k) fluoranthene	83 U
50-32-8	Benzo(a) pyrene	83 U
193-39-5	Indeno(1,2,3-cd)pyrene	83 U
53-70-3	Dibenz(a,h)anthracene	83 U
191-24-2	Benzo(g,h,i)perylene	83 U

### Semivolatiles Surrogate Recovery

d5-Nitrobenzene	79.4%	d5-Phenol	73.0%
2-Fluorobiphenyl	76.1%	2-Fluorophenol	72.0%
d14-p-Terphenyl	81.8%	2,4,6-Tribromophenol	85.4%
d4-1,2-Dichlorobenzene	75.0%	d4-2-Chlorophenol	66.1%



206 621 7523;

ANALYTICAL RESOURCES INCORPORATED

### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

Lab Sample ID: V897B

LIMS ID: 98-6420

Matrix: Soil

Data Release Authorized: LAS

Date extracted: 04/07/98

Date analyzed: 04/09/98

51-28-5

100-02-7

132-64-9

606-20-2

Instrument: finn8

GPC Cleanup: NO

Reported: 04/13/98

Sample No: PL25A-1393

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Sample Amount: 26.2 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1
Percent Moisture: 13.0%

380 U

76 U

380 U

pH: 7.4

CAS Number	Analyte	ug/kg
108-95-2	Phenol	150 U
111-44-4	Bis-(2-Chloroethyl) Ether	150 U
95-57-8	2-Chlorophenol	76 U
541-73-1	1,3-Dichlorobenzene	76 U
106-46-7	1,4-Dichlorobenzene	76 U
100-51-6	Benzyl Alcohol	380 U
95-50-1	1,2-Dichlorobenzene	76 U
95-48-7	2-Methylphenol	150 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	76 U
106-44-5	4-Methylphenol	76 U
621-64-7	N-Nitroso-Di-N-Propylamine	150 U
67-72-1	Hexachloroethane	150 U
98-95-3	Nitrobenzene	76 U
78-59 <b>-</b> 1	Isophorone	76 U
88-75-5	2-Nitrophenol	380 U
105-67-9	2,4-Dimethylphenol	230 U
65-85-0	Benzoic Acid	760 U
111-91-1	bis(2-Chloroethoxy) Methane	76 U
120-83-2	2,4-Dichlorophenol	230 U
120-82-1	1,2,4-Trichlorobenzene	76 U
91-20-3	Naphthalene	76 U
106-47-8	4-Chloroaniline	230 U
87-68-3	Hexachlorobutadiene	150 U
59-50-7	4-Cnloro-3-methylphenol	150 U
91-57-6	2-Methylnaphthalene	76 U
77-47-4	Hexachlorocyclopentadiene	380 U
88-06-2	2,4,6-Trichlorophenol	380 U
95-95-4	2,4,5-Trichlorophenol	380 U
91-58-7	2-Chloronaphthalene	76 U
88-74-4	2-Nitroaniline	380 U
131-11-3	Dimethylphthalate	76 U
208-96-8	Acenaphthylene	76 U
99-09-2	3-Nitroaniline	460 U
83-32-9	Acenaphthene	76 U
51-28-5	2 4-Dinitrophenol	760 U

2,4-Dinitrophenol

2,6-Dinitrotoluene

4-Nitrophenol

Dibenzofuran



### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897B

LIMS ID: 98-6420

Matrix: Soil

Data Release Authorized:

Reported: 04/13/98

Sample No: PL25A-1393

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Sample Amount: 26.2 g-dry-wt

Final Extract Volume: 2.0 mL Dilution Factor: 1:1

Percent Moisture: 13.0% pH: 7.4

Date extracted: 04/07/98 Date analyzed: 04/09/98 Instrument: finn8 GPC Cleanup: NO

CAS Number	Analyte	ug/k	_
121-14-2	2,4-Dinitrotoluene	380	-
84-66-2	Diethylphthalate	76	_
7005-72-3	4-Chlorophenyl-phenylecher	76	_
86-73-7	Fluorene	76	
100-01-6	4-Nitroaniline	380	-
534-52-1	4,6-Dinitro-2-Methylphenol	760	-
86-30-6	N-Nitrosodiphenylamine	76 1	
101-55-3	4-Bromophenyl-phenylether	76	U
118-74-1	Hexachlorobenzene	76 1	Ū
87-86-5	Pentachlorophenol	380 1	U
85-01-8	Phenanthrene	76 1	
86-74-8	Carbazole	76 1	
120-12-7	Anthracene	76 (	_
84-74-2	Di-n-Butylphthalate	76 t	J
206-44-0	Fluoranthene	76 t	J
129-00-0	Pyrene	76 t	J
85-68-7	Butylbenzylphthalate	76 1	J
91-94-1	3.3'-Dichlorobenzidine	380 (	J
56-55-3	Benzo(a) anthracene	76 t	J
117-81-7	bis(2-Ethylhexyl)phthalace	76 T	J
218-01-9	Chrysene	76 T	J
117-84-0	Di-n-Octyl phthalate	76 t	J
205-99-2	Benzo(b) fluoranthene	76 t	J
207-08-9	Benzo(k) fluoranthene	76 t	J
50-32-8	Benzo(a)pyrene	76 U	J
193-39-5	Indeno(1,2,3-cd)pyrene	76 t	
53-70-3	Dibenz(a,h)anthracene	76 I	-
191-24-2	Benzo(g,h,i)perylene	76 L	J

Semivolatiles Surrogate Recovery

d5-Nitrobenzene	75.4%	d5-Phenol	70.7%
2-Fluorobiphenyl	74:.8%	2-Fluorophenol	61.4%
d14-p-Terphenyl	87.2%	2,4,6-Tribromophenol	86.3%
d4-1,2-Dichlorobenzene	78.0%	d4-2-Chlorophenol	67.0%



### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

Lab Sample ID: V897C

LIMS ID: 98-6421

Matrix: Soil

Data Release Authorized: Laid

Reported: 04/13/98

Sample No: PL25A-1394

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 DA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8 GPC Cleanup: NO

Sample Amount: 26.4 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: 13.2%

pH: 7.4

CAS Number	Analyte	ug/kg
108-95-2	Phenol	150 · U
111-44-4	Bis-(2-Chloroethyl) Ether	150 U
95-57-8	2-Chlorophenol	76 U
541-73-1	1,3-Dichlorobenzene	76 U
106-46-7	1,4-Dichlorobenzene	76 U
100-51-6	Benzyl Alcohol	380 U
95-50-1	1,2-Dichlorobenzene	76 U
95-48-7	2-Methylphenol	150 U
108-60-1	2.2'-Oxybis(1-Chloropropane)	76 U
106-44-5	4-Methylphenol	76 U
621-64-7	N-Nitroso-Di-N-Propylamine	150 U
67-72-1	Hexachloroethane	150 U
98-95-3	Nitrobenzene	76 U
78-59-1	Isophorone	76 U
88-75-5	2-Nitrophenol	3.80 U
105-67-9	2,4-Dimethylphenol	230 U
65-85-0	Benzoic Acid	760 U
111-91-1	bis(2-Chloroethoxy) Methane	76 U
120-83-2	2,4-Dichlorophenol	230 U
120-82-1	1,2,4-Trichlorobenzene	76 U
91-20-3	Naphthalene	76 U
106-47-8	4-Chloroaniline	230 U
87-68-3	Hexachlorobutadiene	150 U
59-50-7	4-Chloro-3 methylphenol	150 U
91-57-6	2-Methylnaphthalene	76 U
77-47-4	Hexachlorocyclopentadiene	380 U
88-06-2	2,4,6-Trichlorophenol	380 U
95-95-4	2,4,5-Trichlorophenol	380 U
91-58-7	2-Chloronaphthalene	76 U
88-74-4	2-Nitroaniline	380 U
131-11-3	Dimethylphthalate	76 U
208-96-8	Acenaphthylene	76 U
99-09-2	3-Nitroaniline	460 U
83-32-9	Acenaphthene	76 U
51-28-5	2.4-Dinitrophenol	760 U
100-02-7	4-Nitrophenol	380 U
132-64-9	Dibenzofuran	76 U
606-20-2	2,6-Dinitrotoluene	380 U



## ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897C

LIMS ID: 98-6421

Matrix: Soil

Data. Release Authorized: and

Reported: 04/13/98

Sample No: PL25A-1394

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8
GPC Cleanup: NO

Sample Amount: 26.4 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1
Percent Moisture: 13.2%

CAS Number	Analyte	ug/kg
121-14-2	2,4-Dinitrotoluene	380 U
84-66-2	Diethylphthalate	76 U
7005-72-3	4-Chlorophenyl-phenylether	76 U
86-73-7	Fluorene	76 U
100-01-6	4-Nitroaniline	380 U
534-52-1	4,6-Dinitro-2-Methylphenol	760 U
86-30-6	N-Nitrosodiphenylamine	76 U
101-55-3	4-Bromophenyl-phenylether	76 U
118-74-1	Hexachlorobenzene	76 U
87-86-5	Pentachlorophenol	380 U
85-01 <b>-</b> 8	Phenanthrene	76 U
86-74-8	Carbazole	76 U
120-12-7	Anthracene	76 U
84-74-2	Di-n-Butylphthalace	76 U
206-44-0	Fluoranthene	76 U
129-00-0	Pyrene	76 <b>U</b>
85-68-7	Butylbenzylphchalate	76 U
91-94-1	3,3'-Dichlorobenzidine	380 U
56-55-3	Benzo(a)anthracene	76 U
117-81-7	bis(2-Ethylhexyl)phthalate	76 U
218-01-9	Chrysene	76 U
117-84-0	Di-n-Octyl phthalate	76 U
205-99-2	Benzo(b)fluoranthene	76 U
207-08-9	Benzo(k) fluoranthene	76 U
50-32-8	Benzo(a)pyrene	76 U
193-39-5	Indeno(1,2,3-cd)pyrene	76 U
53-70-3	Dibenz(a,h)anthracene	76 U
191-24-2	Benzo(g,h,i)perylene	76 U

Semivolati.	les Surrogate	Recovery

73.4%	d5-Phenol	65.38
71.4%	2-Fluorophenol	61.3%
88.5%	2,4,6-Tribromophenol	80.0%
67.8%	d4-2-Chlorophenol	63.0₺
	71.4% 88.5%	71.4% 2-Fluorophenol 88.5% 2,4,6-Tribromophenol



ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

e al goldsweld

Lab Sample ID: V897D

LIMS ID: 98-6422

Matrix: Soil

Data Release Authorized: ALA

Reported: 04/13/98

Date extracted: 04/07/98 Date analyzed: 04/09/98

Instrument: finn8 GPC Cleanup: NO

Sample No: PL25A-1395

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98 Date Received: 04/01/98

Sample Amount: 24.7 g-dry-wt

Final Extract Volume: 2.0 mL
Dilution Factor: 1:1
Percent Moisture: 18.9%

pH: 6.7

CAS Number	Analyte	ug/kg
108-95-2	Phenol	160 U
111-44-4	Bis-(2-Chloroethyl) Ether	160 U
95-57-8	2-Chlorophenol	81 U
541-73-1	1,3-Dichlorobenzene	81 U
106-46-7	1,4-Dichlorobenzene	81 U
100-51-6	Benzyl Alcohol	410 U
95-50-1	1.2-Dichlorobenzene	81 U 160 U
95-48-7	2-Methylphenol	81 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	81 U
106-44-5	4-Methylphenol	160 U
621-64-7	N-Nicroso-Di-N-Propy)amine	160 U
67-72-1	Hexachlorocthane	81 U
98-95-3	Nitrobenzene	81 U
78-59-1	Isophoronc	410 U
88-75-5	2-Nitrophenol	240 U
105-67-9	2,4-Dimethylphenol	810 U
65-85-0	Benzoic Acid	81 U
111-91-1	bis(2-Chloroethoxy) Methane	240 U
120-83-2	2,4-Dichlorophenol	81 U
120-82-1	1,2,4-Trichlorobenzene	81 U
91-20-3	Naphthalene	240 U
106-47-8	4-Chloroaniline	160 U
87-68-3	Hexachlorobutadiene	160 U
59-50-7	4-Chloro-3-methylphenol	81 U
91-57-6	2-Methylnaphthalene	410 U
77-47-4	Hexachlorocyclopentadienc	410 U
88-06-2	2,4,6-Trichlorophenol	410 U
95 <b>-</b> 95- <b>4</b>	2,4,5-Trichlorophenol	81 U
91-58-7	2-Chloronaphthalene	410 U
88-74-4	2-Nicroaniline	81 U
131-11-3	Dimethylphthalate	81 U
208-96-8	Acenaphthylene	490 U
99-09-2	3-Nitroaniline	81 U
83-32-9	Acenaphthene	810 U
51-28-5	2,4-Dinitrophenol	410 U
100-02-7	4-Nicrophenol	21 U
132-64-9	Dibenzofuran	410 U
606-20-2	2,6-Dinitrocoluene	•==



#### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897D

LIMS ID: 98-6422

Matrix: Soil

Data Release Authorized: AUA

Reported: 04/13/98

Sample No: PL25A-1395

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Sample Amount: 24.7 g-dry-wt

Final Extract Volume: 2.0 ml

Dilution Factor: 1:1 Percent Moisture: 18.9%

pH: 6.7

Date extracted: 04/07/98 Date analyzed: 04/09/98 Instrument: finn8 GPC Cleanup: NO

	Analyte	. <u> </u>	ug/kg
CAS Number	2,4-Dinitrotoluene		410 U
121-14-2	Diethylphthalate		81 U
84-66-2	4-Chlorophenyl-phenylether		81 U
7005-72-3	Fluorene		81 U
86-73-7	4-Nitroaniline		410 U
100-01-6	4,6-Dinitro-2-Methylphenol		810 U
534-52-1	N-Nitrosodiphenylamine		81 U
86-30-6	4-Bromophenyl-phenylether		81 U
101-55-3	Hexachlorobenzene		81 U
118-74-1			410 U
87-86-5	Pentachlorophenol		81 U
85-01-8	Phenanthrene		81 U
86-74-8	Carbazole		81 U
120-12-7	Anthracene		81 U
84-74-2	Di-n-Butylphthalace		81 U
206-44-0	Fluoranthene		81 U
129-00-0	Pyrene		81 U
85-68-7	Butylbenzylphthalate		410 U
91-94-1	3,3'-Dichlorobenzidine		81 U
56-55 <b>-</b> 3	Benzo(a) anthracene		81 U
117-81-7	bis(2-Ethylhexyl)phthalate		81 U
218-01-9	Chrysene		81 U
117-84-0	Di-n-Octyl phthalate		81 U
205-99-2	Benzo(b) fluoranthene		81 ប
207-08-9	Benzo(k) fluoranthene		81 U
50-32 <b>-</b> 8	Benzo(a)pyrene		81. U
193-39-5	Indeno(1,2,3-cd)pyrene		81 U
53-70-3	Dibenz(a,h)anthracene		81 U
191-24-2	Benzo(g,h,i)perylene		

	Semivolatilas Sur	rogate Recovery	71.1%
d5-Nitrobenzene 2-Pluorobiphenyl d14-p-Terphenyl d4-1,2-Dichlorobe	75.0% 69.8% 83.6%	d5-Phenol 2-Fluorophenol 2,4,6-Tribromophenol d4-2-Chlorophenol	69.8% 92.8% 61.8%



Page 13/19

ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

4. H. (1944) (1941)

Lab Sample ID: V897E

LIMS ID: 98-6423

Matrix: Soil

Data Release Authorized: 674

Reported: 04/13/98

Sample No: PL25A-1396

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8

GPC Cleanup: NO

Sample Amount: 26.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: 13.9%

	·	: ,
CAS Number	Analyte	ug/kg
108-95-2	Phenol	150 U 150 U
111-44-4	Bis-(2-Chloroethyl) Ether	77 U
95-57-8	2-Chlorophenol	77 U
541-73-1	1,3-Dichlorobenzene	
106-46-7	1,4-Dichlorobenzene	77 U
100-51-6	Benzyl Alcohol	380 U
95-50-1	1,2-Dichlorobenzene	77 U
95-48-7	2-Methylphenol	150 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	77 U
106-44-5	4-Methylphenol	77 U
621-64-7	N-Nitroso-Di-N-Propylamine	150 U
67-72-1	Hexachloroethane	150 U
98-95-3	Nitrobenzene	77 U
78-59-1	Isophorone	77 U
88-75-5	2-Nitrophenol	380 U
105-67-9	2,4-Dimethylphenol	230 U
65-85-0	Benzoic Acid	770 U
111-91-1	bis(2-Chloroethoxy) Methane	77 ป
120-83-2	2,4-Dichlorophenol	230 U
120-82-1	1,2,4-Trichlorobenzene	77 ט
91-20-3	Naphthalene	77 U
106-47-8	4-Chloroaniline	230 U
87-68-3	Hexachlorobutadiene	150 U
59-50-7	4-Chloro-3-methylphenol	150 U
91-57-6	2-Methylnaphthalene	77 U
77-47-4	Hexachlorocyclopentadiene	380 U
88-06-2	2.4.6-Trichlorophenol	380 U
95-95-4	2,4,5-Trichlorophenol	380 U
91-58-7	2-Chloronaphthalene	77 U
88-74-4	2-Nitroaniline	380 U
131-11-3	Dimethylphthalate	77 ט
208-96-8	Acenaphthylene	7 <b>7</b> U
99-09-2	3-Nitroaniline	460 U
83-32-9	Acenaphthene	77 U
51-28-5	2,4-Dinitrophenol	770 U
100-02-7	4-Nitrophenol	380 U
132-64-9	Dibenzofuran	<b>7</b> 7 U
606-20-2	2.6-Dinitrotoluene	380 U
	2,2 22	



### ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897E

LIMS ID: 98-6423

Matrix: Soil

Data Release Authorized: ON,3

Date extracted: 04/07/98 Date analyzed: 04/09/98

Instrument: finn8

193-39-5

53-70-3

191-24-2

GPC Cleanup: NO

Reported: 04/13/98

Sample No: PL25A-1396

QC Report No: V897-Boeing Plant II

Project: Plant II

P12 0A3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Sample Amount: 26.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: 13.9%

pH: 7.0

77 U

77 U

	King and the second sec	ug/kg
CAS Number	Analyte	380 U
121-14-2	2,4-Dinitrotoluene	17 U
84-66-2	Diethylphthalate	77 U
7005-72-3	4-Chlorophenyl-phenylether	77 U
86-73-7	Fluorens	380 U
100-01-6	4-Nitroaniline	770 U
534-52-1	4,6-Dinitro-2-Methylphenol	77 ป
86-30-6	N-Nitrosodiphenylamine	77 U
101-55-3	4-Bromophenyl-phenylether	77 U
118-74-1	Hexachlorobenzene	380 U
87-86-5	Pentachlorophenol	77 U
85-01-8	Phenanthrene	77 U
86-74-8	Carbazole	77 U
120-12-7	Anthracene	7 <b>7</b> U
84-74-2	Di-n-Butylphthalate	77 U
206-44-0	Fluoranthene	77 U
129-00-0	Pyrene	77 U
85-68-7	Butylbenzylphthalate	380 U
91-94-1	3,3'-Dichlorobenzidine	77 U
56-55-3	Benzo(a) anthracene	77 U
117-81-7	bis(2-Ethylhexyl)phthalate	<b>7</b> 7 U
218-01-9	Chrysene	77 0
117-84-0	Di-n-Octyl phthalate	<b>7</b> 7 U
205-99-2	Benzo(b) fluoranthene	77 U
207-08-9	Benzo(k)fluoranthene	77 U
50-32-8	Benzo(a) pyrene	77 U
	#_ Jama() 7 (=CAIDVICHE	

Indeno(1.2,3-cd)pyrene

Dibenz(a,h)anthracene

Benzo(g,h,i)perylene

:	Semivolatiles Surro	gate Recovery	69,3%
d5-Nitrobenzene	74.8	d5-Phenor	64.3%
2-Fluorobiphenyl	73.3%	2-Fluorophenol 2,4,6-Tribromophenol	93.3%
d14-p-Terphenyl	85.1%	d4-2-Chlorophenol	64.48
d4-1,2-Dichloroben	zene 71.6%	d4-2-Chiorophenor	



ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

Tophysical Reports on

Lab Sample ID: V897F

LIMS ID: 98-6424 Matrix: Soil

Data Release Authorized:

Date extracted: 04/07/98

Date analyzed: 04/09/98 Instrument: finn8

GPC Cleanup: NO

Reported: 04/13/98

Sample No: PL25A-1397

QC Report No: V897-Boeing Plant II
Project: Plant II

P12 OA3IM

Date Sampled: 03/31/98 Date Received: 04/01/98

Sample Amount: 26.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: 13.4%

		• •
CAS Number	Analyte	ug/kg
108-95-2	Phenol	150 U
111-44-4	Bis-(2-Chloroethyl) Ether	150 U
95-57-8	2-Chlorophenol	77 U
541-73-1	1.3-Dichlorobenzene	77 U
106-46-7	1,4-Dichlorobenzene	77 U
100-51-6	Benzyl Alcohol	380 U
95-50-1	1,2-Dichlorobenzene	77 U
95-48-7	2-Methylphenol	150 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	77 U
106-44-5	4-Methylphenol	77 U
621-64-7	N-Nitroso-Di-N-Propylamine	150 U
67-72-1	Hexachloroethane	150 U
98-95-3	Nitrobenzene	7 <b>7</b> U
78-59-1	Isophorone	77 Ü
88-75-5	2-Nitrophenol	380 U
105-67-9	2,4-Dimethylphenol	230 U
65-85-0	Benzoic Acid	770 U
111-91-1	bis(2-Chloroethoxy) Methane	77 U
120-83-2	2,4-Dichlorophenol	230 U
120-82-1	1,2,4-Trichlorobenzene	77 U
91-20-3	Naphthalene	77 U
106-47-8	4-Chloroaniline	230 U
B7-68-3	Hexachlorobutadiene	150 U
59-50-7	4-Chloro-3-methylphenol	150 U
91-57-6	2-Methylnaphthalene	77 U
77-47-4	Hexachlorocyclopentadiene	380 U
88-06-2	2,4,6-Trichlorophenol	380 U
95-95-4	2,4,5-Trichlorophenol	380 U
91-58-7	2-Chloronaphthalene	77 U
88-74-4	2-Nitroaniline	380 U
131-11-3	Dimethylphthalace	77 U
208-96-8	Acenaphthylene	<b>77</b> U
99-09-2	3-Nitroaniline	460 U
83-32-9	Acenaphthene	77 U
51-28-5	2,4-Dinicrophenol	7 <b>70</b> U
100-02-7	4-Nitrophenol	380 U
132-64-9	Dibenzofuran	77 U
606-20-2	2,6-Dinitrotoluene	380 U
• • • • • • • • • • • • • • • • • • •		



# ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897F

LIMS ID: 98-6424 Matrix: Soil

Data Release Authorized:

Reported: 04/13/98

Sample No: PL25A-1397

QC Report No: V897-Boeing Plant II

Project: Plant II

Pl2 OA3IM

Date Sampled: 03/31/98

Date Received: 04/01/98

Date extracted: 04/07/98

Date analyzed: 04/09/98

Instrument: finn8
GPC Cleanup: NO

Sample Amount: 26.1 g-dry-wt

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1
Percent Moisture: 13.4%

CAS Number	Analyte	ug/kg
121-14-2	2,4-Dinitrotoluene	380 U
84-66-2	Diethylphthalate	77 U
7005-72-3	4-Chlorophenyl-phenylether	77 U
86-73-7	Fluorene	77 U
100-01-6	4-Nitroaniline	380 U
534-52-1	4,6-Dinitro-2-Methylphenol	770 ט
86-30-6	N-Nitrosodiphenylamine	77 U
101-55-3	4-Bromophenyl-phenylether	77 U
118-74-1	Hexachlorobenzene	77 U
87-86-5	Pentachlorophenol	380 U
85-01-8	Phenanthrene	77 U
86-74-8	Carbazole	77 U
120-12-7	Anthracene	77 U
84-74-2	Di-n-Butylphthalate	77 U
206-44-0	Fluoranthene	77 U
129-00-0	Pyrene	77 U
85-68-7	Butylbenzylphthalate	77 U
91-94-1	3,3'-Dichlorobenzidine	380 U
56-55-3	Benzo(a)anthracene	77 U
117-81-7	bis(2-Ethylhexyl)phthalate	77 U
218-01-9	Chrysene	77 U
117-84-0	Di-n-Octyl phthalate	77 U
205-99-2	Benzo(b) fluoranthene	77 U
207-08-9	Benzo(k) fluoranthene	77 U
50-32-8	Benzo(a) pyrene	77 U
193-39-5	Indeno(1,2,3-cd)pyrene	77 U
53-70-3	Dibenz(a,h)anthracene	77 U
191-24-2	Benzo(g,h,i)perylene	77 U

Semivolatiles	8077074	D = = = = = = = .
DOMIACTGITAR	purrodace	Kecovery

d5-Nitrobenzene	76.8%	d5-Phenol	79.6%
2-Fluorobiphenyl	76.6%	2-Pluorophenol	68.0%
dl4-p-Terphenyl	80.3%	2,4,6-Tribromophenol	92.9%
d4-1,2-Dichlorobenzene	78.8%	d4-2-Chlorophenol	70.3%



ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 1 of 2

Lab Sample ID: V897MB

LIMS ID: 98-6419

Matrix: Soil

Data Release Authorized: 8448

Date extracted: 04/07/98

Date analyzed: 04/08/98

Instrument: finn8

GPC Cleanup: NO

Reported: 04/13/98

Sample No: Method Blank

QC Report No: V897-Boeing Plant II

Plant II Project:

Pl2 OA3IM

Date Sampled: Date Received:

Sample Amount: 30.0 g-dry-wt Equiv

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: NA

pH: NA

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
CAS Number	Analyte	ug/kg
108-95-2	Phenol	130 U
111-44-4	Bis-(2-Chloroethyl) Ether	130 U
95-57-8	2-Chlorophenol	67 U
541-73-1	1,3-Dichlorobenzene	67 U
106-46-7	1,4-Dichlorobenzene	67 U
100-51-6	Benzyl Alcohol	330 U
95-50-1	1,2-Dichlorobenzene	67 U
95-48-7	2-Methylphenol	130 U
108-60-1	2,2'-Oxybis(1-Chloropropane)	67 U
106-44-5	4-Methylphenol	67 U
621-64-7	N-Nitroso-Di-N-Propylamine	130 U
67-72-1	Hexachloroethane	130 U
98-95-3	Nitrobenzene	67 U
78-59-1	Isophorone	67 U
88-75-5	2-Nitrophenol	330 U
105-67-9	2,4-Dimethylphenol	200 U
65-85-0	Benzoic Acid	670 U
111-91-1	bis(2-Chloroethoxy) Methane	67 U
120-83-2	2,4-Dichlorophenol	200 U
120-82-1	1,2,4-Trichlorobenzene	67 U
91-20-3	Naphthalene	67 U
106-47-8	4-Chloroaniline	200 U
87-68-3	Hexachlorobutadiene	130 U
59-50-7	4-Chloro-3-methylphenol	130 U
91-57-6	2-Methylnaphthalene	67 U
77-47-4	Hexachlorocyclopentadiene	330 U
88-06-2	2,4,6-Trichlorophenol	330 U
95-95-4	2,4,5-Trichlorophenol	330 U
91-58-7	2-Chloronaphthalene	67 U
88-74-4	2-Nitroaniline	330 U
131-11-3	Dimethylphthalate	67 U
208-96-8	Acenaphthylene	67 U
99-09-2	3-Nitroaniline	400 U
83-32-9	Acenaphthene	67 U
51-28-5	2,4-Dinitrophenol	670 U
100-02-7	4-Nitrophenol	330 U
132-64-9	Dibenzofuran	67 U
606-20-2	2,6-Dinitrotoluene	330 U



ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS

Page 2 of 2

Lab Sample ID: V897MB

LIMS ID: 98-6419

Matrix: Soil

Data Release Authorized: AND

Reported: 04/13/98

Sample No: Method Blank

QC Report No: V897-Boeing Plant II

Project: Plant II

P12 0A3IM

Date Sampled: NA Date Received: NA

Date extracted: 04/07/98

Date analyzed: 04/08/98

Instrument: finn8 GPC Cleanup: NO

Sample Amount: 30.0 g-dry-wt Equiv

Final Extract Volume: 2.0 mL

Dilution Factor: 1:1 Percent Moisture: NA

pH: NA

CAS Number	Analyte	ug/kg
121-14-2	2,4-Dinitrotoluene	330 U
84-66-2	Diethylphthalate	67 U
7005-72-3	4-Chlorophenyl-phenylether	67 U
86-73-7	Pluorene	67 U
100-01-6	4-Nitroaniline	330 Ü
534-52-1	4,6-Dinitro-2-Methylphenol	670 U
86-30-6	N-Nitrosodiphenylamine	67 U
101-55-3	4-Bromophenyl-phenylether	67 U
118-74-1	Hexachlorobenzene	67 U
87-86-5	Pentachlorophenol	330 U
85-01-8	Phenanthrene	67 U
86-74-8	Carbazole	67 U
120-12-7	Anthracene	67 U
84-74-2	Di-n-Butylphthalate	67 U
206-44-0	Fluoranthene	67 U
129-00-0	Pyrene	67 บ
85-68-7	Butylbenzylphthalate	67 U
91-94-1	3,3'-Dichlorobenzidine	330 U
56-55-3	Benzo(a)anthracene	67 U
117-81-7	bis(2-Ethylhexyl)phthalate	67 U
218-01-9	Chrysene	67 U
117-84-0	Di-n-Octyl phthalate	67 U
205-99-2	Benzo(b) fluoranthene	67 U
207-08-9	Benzo(k) fluoranthene	67 บ
50-32-8	Benzo(a) pyrene	67 U
193-39-5	Indeno(1,2,3-cd)pyrene	67 U
53-70-3	Dibenz(a,h)anthracene	67 U
191-24-2	Benzo(g,h,i)perylene	67 U

Samivolatiles Surrogate Recovery

d5-Nitrobenzene	64.48	d5-Phenol	.71.6%
2-Fluorobiphenyl	74.0%	2-Fluorophenol	67.48
d14-p-Terphenyl	65.14	2,4,6-Tribromophenol	66.3
d4-1,2-Dichlorobenzene	79.41	d4-2-Chlorophenol	74.9%



206 621 7523;

ANALYTICAL RESOURCES INCORPORATED

## ORGANICS ANALYSIS DATA SHEET Semivolatiles by GC/MS Page 1 of 1

QC Report No: V897-Boeing Plant II

Project: Plant II P12 0A3IM

Lab Sample ID: V897SB LIMS ID: 98-6419 Matrix: Soil

Data Release Authorized: 84/3 Reported: 04/13/98

LABORATORY CONTROL SAMPLE Date extracted: 04/07/98 analyzed: 04/08/98

Date analyzed: 04/08/98	SPIKE	SPIKE ADDED	RECOVERY	
CONSTITUENT Phenol 2-Chlorophenol 1,4-Dichlorobenzene N-Nitroso-Di-N-Propylamine 1,2,4-Trichlorobenzene 4-Chloro-3-methylphenol Acenaphthene 4-Nitrophenol 2,4-Dinitrotoluene	1810 1680 1200 1090 1210 1720 1460 1640 1220	2500 2500 1670 1670 1670 2500 1670 2500	72.4% 67.2% 71.9% 65.3% 72.5% 68.8% 87.4% 65.6% 73.1% 52.4% 71.9%	
Pentachlorophenol pyrene	1200	1670	11.24	

## Lab Control Surrogate Recovery

d5-Nitrobenzene 2-Fluorobiphenyl d14-p-Terphenyl d4-1,2-Dichlorobenzene	73.6% 74.2% 68.2% 75.6%	d5-Phenol 2-Fluorophenol 2,4,6-Tribromophenol d4-2-Chlorophenol	75.2% 66.7% 69.5% 72.8%
d4-1,2-Dichiolobenia			

Values reported in ug/kg-dry-weight

# APPENDIX D QUALITY CONTROL CHECKLIST

Table 3—OA 3 QA Checklist

De	scription	Criteria	Inspection Method	Inspected by	Approved (initial)
1.	Mark Soil Excavation Area	+- 1 foot	tape measure	Construction Engineer	fov
2.		NA	visual	Construction Engineer	FOV for M.G.
3.	Spill Prevention	place plastic under roll- offs	visual	Construction Engineer	
		no free liquid in soil	visual	Construction Engineer	JOV
		verify no leaks in temporary tanks after liquid placement	visual	Construction Engineer	N/A (Not articable)
4.	Sampling	1 confirmatory bottom samples and 2 sidewall samples spaced over bottom and sides of excavation	visual	Construction Engineer	for
		3 samples from each soil pile	visuaĺ	Construction Engineer	\$6V
5	. Decontamination	decon hoe bucket	observation	Construction Engineer	MY
6	. Backfill	as specified by Boeing	visual- verify before shipment to site	Construction Engineer	for for M.G.
7	. Excavation area and depth	as delineated based on pre-removal soil sample data and to groundwater or as identified otherwise in the field	measure (using tape measure or equivalent). Measure area and depth in 4 corners	Construction Engineer	<b>36√</b>